



MFC (Channel 2) & Vacuum Pump: Not working properly








Temperature not maintained to 100° C



Pressure Profile



Pressure drops from 0.03 mbar to atmospheric pressure (>1.xx mbar) in less than 5 seconds.

Pressure reading difference between analog & digital pirani gauge





Leak Test

- Plastic O-rings
- Metallic joints that holds the O-rings with the tube.

Other things to consider...

- One way purge valve.
- Preview window.
- Command to abort a recipe (Needs an updated one)
- Vacuum pump works occasionally.