

Meridian Pharmaceuticals Pvt. Ltd.

Plant: Baddi, Himachal Pradesh, India

DEVIATION REPORT — DEV-2026-015

Deviation ID	DEV-2026-015
Date Raised	15-Jan-2026
Raised By	Internal Audit Team (Quarterly Equipment Compliance Audit)
Equipment Reference	TCM-04 (Tablet Compression Machine)
Classification	Major
Related Deviation	DEV-2026-014 (weight variation OOS, Batch MP-PCM-2602) — this event identified as contributing cause

1. Description

During the quarterly equipment compliance audit, it was observed that preventive maintenance and punch-wear inspection for TCM-04, scheduled per SOP-ENG-007 at a 90-day frequency, was overdue by 12 days. The equipment maintenance log (Log Ref: ENG-LOG-TCM04-2025Q4) showed no record of inspection between the due date and the audit date, during which Batch MP-PCM-2602 was compressed on the same machine.

2. Immediate Action

TCM-04 taken off the production schedule pending inspection. Preventive maintenance and punch-wear check performed same day by Engineering.

3. Investigation / Root Cause

Root cause traced to a manual, calendar-based tracking system for preventive maintenance due dates with no automated alert; the due-date entry for TCM-04 was overlooked during the year-end holiday period. This is assessed as a contributing root cause to DEV-2026-014.

CAPA Reference: CAPA-2026-012

#	CAPA Action	Target Date
1	Perform overdue preventive maintenance and punch-wear inspection on TCM-04	15-Jan-2026
2	Implement automated calibration/PM-due alert system across all Class-A production equipment	28-Feb-2026
3	Audit PM schedules for all other compression and granulation equipment for similar gaps	11-Jan-2026

Closure

Audit of remaining Class-A equipment found no further overdue PM schedules. CAPA-2026-012 automated alert system implemented and verified across TCM-04, RMG-02, FBD-01 and OB-02. Closed by: Dr. Sunil Mehta, Quality Head, 03-Mar-2026.