EX.No.-1.2 – DESIGN AND DRAFT THE GIVEN 2D SKETCHES IN MODELLING SOFTWARE

DATE:07.10.2026

AIM:

To design and draft the given 2D sketch with proper dimensions using Autodesk Fusion 360 software.


REQUIREMENTS:

1. Autodesk Fusion 360
2. Windows 10 operating system
3. 16 GB RAM (integrated graphics recommend 1 GB or more)
4. 2.5 Mbps or faster download and 500 Kbps or faster upload speed


PROCEDURE:

1. Launch Autodesk Fusion 360 and create a new design file.

2. Click on the Create Sketch option and choose a suitable plane for drawing the given 2D sketch.




3. Select the appropriate sketch tools, such as Line, Circle, Arc, Rectangle and Polygon, to construct the required geometric shapes.



4. Apply the necessary dimensions and constraints to maintain the correct size and position of the sketch.


5. Use editing commands such as Trim, Mirror, Move and other modifying tools to refine



the drawing and remove unwanted portions.
6. Check the measurements using the Inspect tool and make the required corrections to match the given dimensions.
7. Click Finish Sketch to complete the 2D drawing.
8. Open the Drawing workspace and select the appropriate drawing settings to prepare the sketch for drafting.
9. Choose the ISO standard and arrange the drawing appropriately on the drawing sheet.
10. Verify the completed drawing, save the design file and ensure that the sketch matches the given reference.


SKETCH:

Given 2D sketch.



OUTPUT:

The 2D sketch was designed and drafted using Autodesk Fusion 360.



RESULT:

Thus, the given 2D sketch was successfully designed and drafted with the required dimensions using Autodesk Fusion 360 software.