CLIENT MEETING / 28 OCTOBER 2026

Your client demo, step by step.

A 25-30 minute guided presentation, with optional deeper control demonstrations.

THE STORY TO TELL

One customer order. Connected departments. Visible controls at every handoff.

OPENING SCRIPT

"This is a working discovery prototype for Triveni Wires. We will follow one sample GI-wire order through production, quality, packing, dispatch and finance, then show the supporting departments. Please tell us where the flow differs from your actual operation."

PRESENTATION ROUTE

Prepare and load data / show the overview / follow the order and material / prove a blocked shipment / release, pack and dispatch / invoice and collect / tour supporting modules / agree discovery next steps.

Positioning: demonstrate industry-aligned control concepts. Do not describe this as certified software, secure production authorization, a live integration or an approved Triveni factory process.

CLIENT MEETING / 28 OCTOBER 2026

Prepare before the client joins.

Allow 10 minutes for setup and a rehearsal on the exact device you will use.

01 Open and initialize

DO Open http://localhost:8765/ on the same computer, then refresh. Click Load presentation data / Load sample dataset.

SAY “All names, figures and production assumptions are fictional demonstration data.”

CHECK Overview: open order 2,500 kg; ready 500 kg; quality hold 1,000 kg; dispatched 2,500 kg.

02 Set up your presentation

DO Use a wide browser window. Start as Administrator using the Acting role selector. Keep Demo guide and Controls & audit visible.

SAY “We have mapped all 16 proposed modules, with one connected manufacturing scenario.”

CHECK Load presentation data replaces demo edits. Do not click Reset demo during the main presentation: that restores the starting scenario.

BACKUP PLAN

Keep Triveni_Wires_Working_Demo.html downloaded locally. If the local server is unavailable, open that file in your browser and load presentation data again. Rehearse it beforehand; browser storage is separate from localhost. The hosted link has not received the latest updates.

CLIENT MEETING / 28 OCTOBER 2026

Show the business before the controls.

Minutes 0-6 / Use the loaded presentation dataset. No new transaction is needed yet.

03 Overview / CRM & sales

DO Show the overview and the 16-module map. Open CRM & sales. Point to SO-1001, the 5,000 kg order, 2,500 kg shipped and 2,500 kg balance.

SAY “Sales and the factory share one fulfilment position. The customer requirement is retained with the order.”

CHECK Sample customer: Sample Infrastructure Co. Rate: INR 85/kg; order value before tax: INR 425,000. CRM stage: Won.

04 Planning / execution / inventory

DO Open Planning, then Manufacturing execution. Show completed PO-2001. Open Inventory and explain the five coils and their statuses.

SAY “Production records actual consumption and output. Coating adds weight, so we reconcile steel, zinc, output and scrap explicitly.”

CHECK 3,940 kg steel + 80 kg zinc = 4,000 kg output + 20 kg scrap. Raw balances: 2,060 kg steel and 120 kg zinc.

Ask the client: “Which production stages, coil sizes and material-loss rules would differ in your factory?” The demo starts with prepared intermediate wire; it does not model the complete rod-to-wire route.

CLIENT MEETING / 28 OCTOBER 2026

Prove that the controls actually act.

Minutes 6-12 / Follow these steps in sequence so the expected balances remain correct.

05 Demonstrate a blocked action

DO As Administrator, open Warehouse and click Pack for FG-004: role permission is denied. Switch Acting role to Dispatch. Open Dispatch, select only FG-005 and click Validate & dispatch.

SAY “Permissions restrict transaction posting. Held material must not leave the factory.”

CHECK FG-005 is blocked. In this prototype the packing check may appear first because this held coil is also unpacked. Show its Hold status in Quality; do not promise a specific error message.

06 Inspect and release FG-004

DO Switch to Quality. Open Quality / Inspect on FG-004. Keep diameter 3.00 mm and coating 110 g/m²; enter a note and click Save inspection.

SAY “Quality records the measurements before releasing the material. These demonstration limits must be replaced by your approved specifications.”

CHECK FG-004 changes Pending / Released. Released stock becomes 1,500 kg. FG-005 remains on Hold at 90 g/m².

Avoid inspecting FG-002 or FG-003 to demonstrate a change: they have already shipped and are protected from reclassification. FG-004 is the intended inspection example.

CLIENT MEETING / 28 OCTOBER 2026

Complete the physical and financial handoff.

Minutes 12-18 / Continue from the FG-004 quality release on the previous page.

07 Pack / dispatch / trace

DO Switch to Warehouse / Pack FG-004. Switch to Dispatch. Select only FG-004; leave 1,000 kg and the default vehicle/tare. Click Validate & dispatch. Open its Packing list.

SAY “Only released and packed material can ship. Stock and the order balance update together. Each shipment retains coil identity.”

CHECK DSP-003: 1,000 kg. Total dispatched: 3,500 kg. Order balance: 1,500 kg. Packing list downloads as HTML; open it and print to PDF if desired.

08 Invoice and collect

DO Switch to Finance. Open Finance / Create demo invoice for DSP-003. Find the corresponding new invoice (normally INV-002). Click Record receipt, enter 25,000 and save.

SAY “Billing is derived from the physical shipment. Collections reduce that invoice’s outstanding amount.”

CHECK New invoice: INR 85,000; paid: INR 25,000; balance: INR 60,000. DSP-002 remains uninvoiced. No GST, real payment or ledger posting occurs.

Open Coil traceability and select FG-004: show RM-STEEL-01 + ZN-01 / PO-2001 / inspection / DSP-003. FG-003 separately demonstrates a 500 kg shipment with a 500 kg coil balance.

CLIENT MEETING / 28 OCTOBER 2026

Tour the remaining departments with purpose.

Minutes 18-25 / Keep this tour brisk; choose deeper examples based on client interest.

Administration	Show six sample users, active/inactive status and the proposed approval matrix. These are demonstration identities.
Product masters	Switch to Planner. Edit GI-3-110 coating from 110 to 115. Save; show R3 in Controls & audit. Existing order specifications stay fixed.
Procurement	Switch to Warehouse. Receive PUR-003 once. Steel stock rises from 2,060 to 4,060 kg; the received order cannot be posted twice.
Costing	Show actual demo quantities with assumed rates. Total cost: INR 268,200; unit cost: INR 67.05/kg (display rounds to INR 67).
Maintenance	Open MT-002, currently In progress. Click Close task. Explain the maintenance history; it does not block machine planning in this demo.
HR & payroll	Show five fictional employees and attendance. Daily estimate starts at INR 3,720. Toggle attendance to demonstrate recalculation.
Reports	Show live released/pending/held quantities, production and fulfilment. Click Export snapshot for the CSV report.
Integrations	Show the five simulated checks. Run a sample check; explain that no accounting system, scale, machine or external service is contacted.

CLIENT MEETING / 28 OCTOBER 2026

Make governance visible. Close on discovery.

Minutes 25-30 / Show evidence and turn the demonstration into a requirements conversation.

09 Controls & audit

DO Open Controls & audit. Show the seeded approvals: Sales / Finance and Operator / Planner. Show the specification revision and blocked-action history. Click Export audit.

SAY "These illustrate role separation, approval evidence and a change history. Production implementation will enforce them on the server with protected audit records."

CHECK Audit export is JSON. This browser-local history is not tamper-proof. Loading data resets the demonstration evidence.

10 Ask for operational validation

DO Ask which routes, units, quality limits, approvals, accounting software and reports differ. Nominate a sponsor and process owners; agree a factory walkthrough and sample records.

SAY "The next step is to validate your real workflows, agree the pilot scope and acceptance criteria, then estimate implementation."

CHECK Leave with owners, dates and evidence requests. Do not promise complete compliance, a final price or a go-live date from the prototype alone.

Suggested final line: "Which three operational problems should the first release solve, and which product family should we use for the pilot?"

CLIENT MEETING / 28 OCTOBER 2026

Optional live approvals & quick recovery.

Use this only after the main presentation; resetting clears the loaded transaction scenario.

MAKER / CHECKER WALKTHROUGH

1. Reset demo / Reset sample data. Switch to Sales; create the default order.
2. Controls & audit / submit Sales order. Attempt approval as Sales: denied.
3. Switch to Finance; approve Sales order.
4. Switch to Planner; open Planning / Create production order.
5. Switch to Operator; Controls & audit / submit Production.
6. Switch to Planner; approve Production. Switch to Operator; open Manufacturing execution and record the balanced defaults.
7. Show the audit evidence. Load presentation data again to restore the complete scenario.

IF SOMETHING DOES NOT MATCH

Wrong balances? Reload presentation data and restart at step 3.
Permission denied? Check the Acting role selector.
Dispatch blocked? Check approval, quality, packing, available weight and order balance.
No new invoice? Check whether that shipment already has one.
Missing new buttons? Refresh the page or reopen the latest standalone file.

Verification: functional checks cover roles, approvals, stock, material balance and dispatch guards. This revision has not had a visual browser walkthrough because browser control was disabled. Rehearse before presenting.