

This calibration is not necessary for everyone, if your drawbot Cant draw a square beautiful, You can do as follow,this calibration is only for firmwire above V6

Small arm and big arm is 200mm Big arm Parallel base side The size of the arm is 45 degrees Then send M700, after 10 sec, Return "calibration finished" means OK