

Figure 7.2. Hidden terminal problem with RTS-CTS-Data-ACK scheme.




Figure 7.3. Exposed terminal problem.