



Extruder wire clamp installation instruction








This two side should be locked first





Use allen wrench or screwdriver to unlock the clamp

