

Scanned by TapScanner

Transition prabability matrix					
01d 00 01 10 11					
019	00	01	10		
00'	0	43	8/3	0	
01	1/3	0	2/3	0	
10	0	0	0		
11)	2/3	1/3	O	0	
entropy = $-\frac{1}{2} = \frac{1}{2} = 1$					