Checklist for ERT equipment

Computer	Laptop GETAC (large)	There are 3 of them, numbered 0, 1, 2. "0" works for ERT
	Laptop wall plug charger	
	Laptop car charger adaptor	
	Spare laptop batteries	
	Separate GETAC battery charger for 2 x laptop batteries	
	USB dongle if license is needed for 2d-inv	
Station	TIGRE station	(in medium size black box)
	Cable for battery connect	
	Cable for laptop Ethernet connect	
	User manual	
12 V Batteries	1 + 1 spare	
	Wall plug 12 V charger 2x	+
Spools and electrodes	64 setup: 2 x large boxes (32+32el & 1+1 spool)	
	128 setup: add 2 x boxes add 2 x extension cables	
Measuring tools	Trundle (measuring) wheel	
	Tape measures	
Positioning tools	GPS rover emlid receiver	
	GPS base emlid receiver	
	2 x Poles for GPS receivers not mandatory if GPS on ground level	
	Emlid app on smartphone	
	Passwd: emlidreach	
	Save CSV to smartphone!!	
Transporting gear	2-wheeled sack truck	
	Open frame backpack	
	Puncture-proof wheel cart	
First aid kit		
Hi-vis jackets		