PROGRESS REPORT

tkLayout developers meeting

Stefano MARTINA

stefano.martina@cern.ch

European Organization for Nuclear Research



Custom supports

```
Support {
  type custom
  customZMin 2300
  customRMin 200
  customLength 600
  customDir vertical
 Component {
    componentName supp
    Element {
      elementName Steel
      quantity 1000000
      unit g
```

Top/bottom supports

```
Support {
  type top //or bottom
  Component {
...
```

Auto supports

```
Support {
  type auto
  autoPosition 500

Component {
```

Done

- √ dump masses
- √ corrected bug in services inversion in Z
- √ found strange behavior in second level station output
- √ classes for interpretation of support config file

To do

- √ investigate second level station bug
- ? changing conversion station input rules from g to g/m
- √ create inactive surfaces for supports
- ✓ implement the (simple) algorithm for top/bottom/auto positioning