

Plant Audit Non-Conformance Report - Klang Manufacturing Facility

Audit Date: 28-Apr to 02-May 2026 | Audit Type: Internal QMS Audit (ISO 9001:2015) | Lead Auditor: Vijay Subramaniam | Auditee: Klang Plant Management | Report Date: 12-May-2026

1. Audit Scope and Methodology

Five-day internal audit covering: production planning, manufacturing operations, quality control, calibration, document control, training records, customer complaint handling, and management review. Audit conducted in accordance with ISO 19011:2018 guidelines. Audit team: 4 auditors, total 80 audit hours.

2. Summary of Findings

Category	Count	Examples
Major Non-Conformance	2	NCR-2026-014, NCR-2026-017
Minor Non-Conformance	8	NCR-2026-015 through NCR-2026-022
Observation	14	OBS-2026-018 through OBS-2026-031
Opportunity for Improvement	6	OFI-2026-008 through OFI-2026-013

3. Major Non-Conformance Details

NCR-2026-014 (Major) - Calibration of critical measurement equipment

Standard: ISO 9001:2015 Clause 7.1.5.2. Three out of fourteen critical pressure gauges in Line K-201 had expired calibration certificates (expired 14-Jan-2026, used through 28-Apr-2026). Root cause: calibration schedule alert mechanism failed silently after CMMS upgrade in December 2025.

Required Corrective Action: (a) immediate withdrawal and recalibration of affected gauges; (b) impact assessment on production from 14-Jan-2026 onward; (c) review of all calibration certs across all lines; (d) CMMS alert mechanism fix. Target close date: 30-May-2026.

NCR-2026-017 (Major) - Customer complaint handling timeliness

Standard: ISO 9001:2015 Clause 9.1.2 + internal SOP. SLA for customer complaint acknowledgement is 24 hours and resolution within 14 days. Audit sample of 50 complaints from Q1 2026 showed: 18% breached acknowledgement SLA, 28% breached 14-day resolution SLA. Root cause: complaint routing tool migration in February 2026 caused mis-routing for 6 weeks.

Required Corrective Action: (a) root-cause complaint routing fix verified; (b) overdue complaints triaged and closed by 31-May; (c) SLA reporting dashboard restored; (d) cross-check sample to be re-audited in October 2026. Target close date: 30-Jun-2026.

4. Minor Non-Conformance Summary

NCR No.	Area	Brief Description	Owner	Target Close
NCR-2026-015	Training Records	4 operators missing annual refresher	HR Manager	30-Jun-2026
NCR-2026-016	Document Control	Obsolete SOP revision in use at WS-K204	QA Manager	14-May-2026
NCR-2026-018	Internal Audit	Q4-2025 audit overdue (planned Nov-25)	QA Manager	31-May-2026
NCR-2026-019	Mgmt Review	Mgmt review minutes incomplete - no action tracker	Plant Mgr	14-May-2026
NCR-2026-020	Risk Register	Top-10 risks not reviewed in last 9 months	Plant Mgr	30-Jun-2026
NCR-2026-021	Supplier Eval	3 of 12 strategic suppliers no annual eval FY2025	Procurement	30-Jun-2026
NCR-2026-022	PPE Compliance	Hearing protection not consistently used in Line K-203	Shift Sup	21-May-2026

5. Auditor Recommendation

Despite the two Major NCRs noted, the QMS is generally operating effectively. We recommend continued certification subject to satisfactory closure of all Major NCRs by 30-Jun-2026. Re-audit of NCR-2026-014 and NCR-2026-017 to be performed in July 2026.

6. Lead Auditor Signature

Vijay Subramaniam (Lead Auditor) | Date: 12-May-2026 | Distribution: Plant GM, Group QA Director, Audit Committee