

QA Failed Test Result Report - Batch ZA-2026-2188-A

(Mawar Body Wash 250ml)

Batch: ZA-2026-2188-A | Product: Mawar Body Wash 250ml (SKU MW-BW-250-OR) | Production Date: 08-May-2026 | Lab Reference: QA-2026-4488 | Test Date: 09-May-2026

1. Batch Information

Field	Value
Batch Quantity	14,840 bottles
Production Line	Line BR-2 at Klang Plant
Shift	Shift B (14:00-22:00)
Shift Supervisor	Ahmad bin Hassan
Hold Status	Quality Hold - DO NOT release
Hold Location	Quarantine Bay Q-08

2. Failed Test Parameters

Parameter	Specification	Result	Status
pH	6.0 - 7.0	5.6	FAIL (out of spec, below LSL)
Viscosity (cP)	8,000 - 12,000	7,200	FAIL (out of spec, below LSL)
Active surfactant	12.0 - 14.0%	12.8%	PASS
Preservative	0.30 - 0.50%	0.42%	PASS
Total Plate Count (CFU/g)	< 100	< 10	PASS
Yeast and Mould (CFU/g)	< 10	< 1	PASS
Appearance	Clear orange liquid	Clear pale orange	PASS
Fragrance	Match standard	Match standard	PASS

3. Investigation Findings

Initial investigation indicates pH and viscosity deviation likely due to: (a) Citric Acid charging weighed 2.4kg over target due to mis-calibrated load cell on Tank LT-203 (calibration check found offset of +1.8kg); (b) Carbomer addition rate slower than spec - 14 minute hold rather than 8-minute hold caused under-thickening. Both contributory factors confirmed via batch sheet and DCS trend review.

4. Disposition Decision

Batch CANNOT be released as-is. Two reprocessing options under evaluation: (a) Reprocess with Caustic Soda to lift pH + Carbomer slurry to recover viscosity - estimated cost MYR 4,800 + 6 hr line time; (b) Scrap and reissue raw material credit - estimated value loss MYR 18,400. Final decision authority: QA Manager Lim Mei Ling, awaiting customer impact review by 14-May-2026 13:00.

5. Corrective Actions

- Load cell LT-203 recalibration completed 10-May-2026 06:30
- All load cells across the line scheduled for early recalibration by 16-May-2026

- Process timer SOP refresher session for all shift operators by 21-May-2026
- Failure mode added to FMEA review - update by 31-May-2026
- Root-cause investigation report due by 23-May-2026 (Owner: Vijay Subramaniam)

6. Sign-off

QA Analyst: Siti Aishah (10-May-2026) | QA Manager: Lim Mei Ling (pending) | Production Manager: Ahmad bin Hassan (pending) | Distribution: Plant Manager, Group QA Director, Quality Council