

Workpiece (top view)

Y = 2.9132

Y = 0.4489

Y = 0.1755

Y

X

step-over
(Y axis)

Same depth (Z), feed (F), and radial engagement → near-identical sensor signatures