



Physical Interpretation: Key Sensor Channels Across Toolpath Types


*Magnetic field disturbance
from motor currents*



*Vertical vibration
at workpiece*



*Y-axis motor
magnetic field*



*Cutting torque
proxy*

