## **Report Type: Patrolman**

Generated On: 20250321\_100006

862491071191777 P3(406.612-410.000), 862491071218836 P4(410.000-431.150), 862491071251027 P9(426.000- 429.181), 862491071255598 P7(419.647-422.350), 862491071257263 P1(400.260-403.000), 862491071258857 P10(429.181-432.403), 862491071262099 P12(435.661-	Pway	Section	Device was off	Beat not covered	Beat completed successfully	Overspeed
438.891), 862491071267262 P11(432.403-435.661), 862491071272932 P5(413.150-416.168), 862491071273310 P2(403.000-406.612), 862491071273724 P8(422.350- 426.000), 862491071332611 P6(416.168-419.647)	SSE/PW/BRGY	SEC/PW/BRGY	P4(410.000-431.150), 862491071251027 P9(426.000-429.181), 862491071255598 P7(419.647-422.350), 862491071257263 P1(400.260-403.000), 862491071258857 P10(429.181-432.403), 862491071262099 P12(435.661-438.891), 862491071267262 P11(432.403-435.661), 862491071272932 P5(413.150-416.168), 862491071273310 P2(403.000-406.612), 862491071273724 P8(422.350-			

System Report Generated on 2025-03-21 10:00:06