Report Type: Keyman

Generated On: 20250320_170006

Pway	Section	Device was off	Beat not covered	Beat completed successfully	Overspeed
SSE/PW/DB	SEC/PW/DB	860103069705391 K3(39.300- 47.700), 860103069823277 K6(10.000-20.000), 860103069829191 K1(27.000-31.300), 862491071183964 K13(73.000- 82.000), 862491071216129 K15(0.500-6.500), 862491071255267 K19(29.000-36.500), 862491071258840 K11(55.000- 64.000), 862491071267643 K8(31.000-38.400), 862491071267775 K10(46.600-55.000), 862491071279986 K5(1.000- 10.000), 862491071320491 K7(20.000-28.000), 862491071326340 K12(64.000-73.000), 862491071331746 K9(38.400- 46.600), 862491071331811 K14(82.000-101.000)	860103069705250 K2(31.300-39.300), 862491071191124 K18(21.500-29.000), 862491071215634 K4(47.300-53.800), 862491071273161 K16(6.500-14.500), 862491071327926 K17(14.500-21.500)	862491071165375 K21(44.500-50.560), 862491071326514 K20(36.500-44.500)	862491071215634 K4(47.300- 53.800)

System Report Generated on 2025-03-20 17:00:06