Report Type: Patrolman

Generated On: 20250315_100006

SSE/PW/DB SEC/PW/DB 860103069700749 P6(36.500-44.500), 860103069711480 P3(14.500-21.500), 860103069735869 P9(31.300-39.300), 860103069756188 P8(27.000-31.300), 860103069822857 P2(6.500-14.500), 860103069833706 P5(29.000-36.500), 862491071218083 P4(21.500-29.000), 862491071219370 P1(0.500-6.500), 862491071219412 P11(47.300-53.800), 862491071279341 P7(44.500-50.560), 862491071280331 P10(39.300-47.700)	Pway	Section	Device was off	Beat not covered	Beat completed successfully	Overspeed
1 10(05:500 41:100)	SSE/PW/DB	SEC/PW/DB	P3(14.500-21.500), 860103069735869 P9(31.300-39.300), 860103069756188 P8(27.000-31.300), 860103069822857 P2(6.500-14.500), 860103069833706 P5(29.000-36.500), 862491071218083 P4(21.500-29.000), 862491071219370 P1(0.500-6.500), 862491071219412 P11(47.300-53.800),			

System Report Generated on 2025-03-15 10:00:06