## Report Type: Keyman

Generated On: 20250323\_170009

Pway	Section	Device was off	Beat not covered	Beat completed successfully	Overspeed
SSE/PW/ND	SEC/PW/ND		860103069699404 K8(45/300-52/600), 860103069699529 K12(75/200-82/300), 860103069716869 K3(10.500-17.400), 860103069752039 K13(82/300-90/300), 862491071213969 K15(98.100-105.300), 862491071214041 K5(23.500-30.450), 862491071215048 K9(52.600-60.200), 862491071306276 K6(30.450-37.644)	860103069699255 K4(17.400- 23.500), 860103069791284 K11(68.000-75.200), 862491071214306 K14(90.300- 98.100), 862491071215428 K7(37.644-45.300), 862491071215469 K10(60.200- 68.000), 862491071215741 K1(1.129-4.000), 862491071280067 K2(4.000- 10.500)	860103069791284 K11(68.000-75.200), 862491071215469 K10(60.200-68.000)
System Depart Consisted on 2025 02 22 17:00:00					

System Report Generated on 2025-03-23 17:00:09