Report Type: Keyman

Generated On: 20250328_170010

Pway	Section	Device was off	Beat not covered	Beat completed successfully	Overspeed
SSE/PW/SVL	SEC/PW/SVL	862491071215535 K11(64.310- 70.757)	860103069791664 K10(57.841-64.356), 862491071215972 K12(70.757-77.279)	860103069699289 K6(32.187-38.56), 860103069789544 K4(19.416-25.694), 860103069790278 K2(7.222-12.840), 860103069791508 K8(45.030-51.499), 862491071215170 K1(1.281-7.222), 862491071215717 K7(38.560-45.030), 862491071215964 K5(25.694-32.187), 862491071322448 K9(51.499-57.841), 862491071332066 K3(12.840-19.416)	

System Report Generated on 2025-03-28 17:00:10