Report Type: Patrolman

Generated On: 20250324_100003

860103069704972 P2(271.62-274.09), 860103069713320	Pway	Section	Device was off	Beat not covered	Beat completed successfully	Overspeed
SSE/PW/URN SEC/PW/URN SEC/PW/URN P8(297.85-293.853), 860103069754191 P5(280.25-285.2), 860103069757392 P7(290.1-293.853), 860103069791060 P6(290.1-285.2), 860103069823988 P1(271.62-268.89), 860103069824051 P4(277.09-280.25), 862491071216236 P3(277.09-274.09), 862491071219107 P9(297.85-302.06)	SSE/PW/URN	SEC/PW/URN	P8(297.85-293.853), 860103069754191 P5(280.25-285.2), 860103069757392 P7(290.1-293.853), 860103069791060 P6(290.1-285.2), 860103069823988 P1(271.62-268.89), 860103069824051 P4(277.09-280.25), 862491071216236			