## Report Type: Keyman

Generated On: 20250314\_170002

Pway	Section	Device was off	Beat not covered	Beat completed successfully	Overspeed	
SSE/PW/URN	SEC/PW/URN	860103069707249 K4(273.855- 275.736), 860103069754431 K1(268.89-269.944), 860103069790237 K3(271.551-273.855), 862491071160400 K6(277.483- 279.735), 862491071215949 K10(289.832-293.323), 862491071219297 K9(286.539- 289.832), 862491071219701 K2(269.944-271.551)		860103069715358 K11(293.323-297.064), 860103069835438 K8(282.58-286.539), 862491071219479 K12(297.064-300.049), 862491071219586 K7(279.735-282.58)	860103069835438 K8(282.58- 286.539)	
Out to a December 2 and						

System Report Generated on 2025-03-14 17:00:02