|--|

## Report Type: Keyman

Generated On: 20250308\_170007

Pway	Section	Device was off	Beat not covered	Beat completed successfully	Overspeed
SSE/PW/DB	SEC/PW/DB	860103069705391 K3(39.300- 47.700), 860103069823277 K6(10.000-20.000), 860103069829191 K1(27.000- 31.300), 862491071183964 K13(73.000-82.000), 862491071216129 K15(0.500- 6.500), 862491071258840 K11(55.000-64.000), 862491071267643 K8(31.000- 38.400), 862491071267775 K10(46.600-55.000), 862491071279986 K5(1.000- 10.000), 862491071320491 K7(20.000-28.000), 862491071326340 K12(64.000- 73.000), 862491071331746 K9(38.400-46.600), 862491071331811 K14(82.000- 101.000)	862491071191124 K18(21.500- 29.000), 862491071273161 K16(6.500- 14.500)	860103069705250 K2(31.300-39.300), 862491071165375 K21(44.500-50.560), 862491071215634 K4(47.300-53.800), 862491071255267 K19(29.000-36.500), 862491071326514 K20(36.500-44.500), 862491071327926 K17(14.500-21.500)	862491071215634 K4(47.300-53.800), 862491071255267 K19(29.000-36.500), 862491071273161 K16(6.500-14.500), 862491071326514 K20(36.500-44.500)

System Report Generated on 2025-03-08 17:00:07