

Part Number: QAL-0027

Revision: B

Effective Date: 6/17/2016

TRAVELER: Q5179-0050, Tesseract XL-HD

Part Information								
The following section contains information about the assembly.								
Part #	Q5179-0050							
Revision	A							
Description	ASSY, Tesseract XL-HD							
Serial #	000564							
Date Recorded	2/15/2022 8:29:17 PM							
	Component	Part Number	Serial #					
Internal Components	Tesseract XL-HD Optical Column	Q5179-0053	000497					
	Diffractive Optic Element	AFCL-GU3211B	58148-132 A					
	Iodine Board	BAPI22	FV41072004KJMX221					

Requirement Description	Requirement	Measurement		In Spec YES/NO		Measurement Method
DOE Surface to Collimated Beam Tip/Tilt Error (Mean)	≤ 50 arcseconds	35.3	arcseconds	/		Auto-collimator
DOE to Mechanical Interface Clocking Error	≤ 0.1°	0.0013	0	'		Spot Pattern Image Processing
Collimated Beam to Mechanical Interface Tip/Tilt Error	≤ 2 arcminutes	0.37	7 arcminutes			Spot Pattern Image Processing
Collimated Beam Transmitted Wavefront Error at 532nm, Single Pass Peak to Valley	≤ 0.50 wave	0.47	wave	V		Shack Hartmann Wavefront Sensor
DOE Reflected Wavefront Error at 633nm, Peak to Valley	≤8 wave	5.1208	wave	~		Zygo Interferometer Wavefront Measurement
Diffractive Optic Orientation (Vx or Vy)	V _Y	Vy	-	~		Visual Inspection

Quality Check Description Result Pass/Fail		Timestamp	
Calibration Data	✓	7/23/2021 8:58:35 AM	
QC Camera	~	2/15/2022 8:24:37 PM	
QC Power Meter	'	2/15/2022 8:03:57 PM	



Part Number: QAL-0027


Revision: B

Effective Date: 6/17/2016


Additional Information

The following section includes any additional information used to generate results. Include graphs, images, and calculations as needed.

DOE Reflected Wavefront Error at 633nm, Peak to Valley



Collimated Beam Transmitted Wavefront Error at 532nm, Single Pass Peak to Valley





Part Number: QAL-0027

Revision: B

Effective Date: 6/17/2016

