



CALVADOS Installation Manual

pmdtechnologies ag – 2019-08-20


© 2019 **pmd**technologies ag confidential www.pmdtec.com|can you imagine

Outline

- Required operating system:
 - Windows 7 64bit
 - Windows 10 64bit
- Required hardware:
 - PC with connection ports for frame grabber (e.g. USB3)
 - Up and running frame grabber solution
 - Connection cables and power cords
 - ToF modules to operate
 - All required hardware listed in pmd documentation (e.g. calibration One Box, Validation Box, LTS, integrating sphere, power meter...)


Software download and installation (1)

- Download link will be provided by pmd.
- Please enter password (password will be provided by pmd).
- Download "pmd_Calibration_and_Validation_Software.exe".
- Execute "pmd_Calibration_and_Validation_Software.exe".
- Accept license agreement:



Software download and installation (2)


- If you install CALVADOS software for the first time, or have fully uninstalled a previous version:
 - Please execute: "pmd_ToF_Calibration_and Validation_Software_vx-y-z_20yy-mm-dd_full.exe"
 - Use default installation path (C:\Program Files\pmdtechnologies_ag\pmd_Calibration_and_Validation_Software) or define path of choice and click on install button
- If you wish to update an existing CALVADOS installation:
 - Please execute: "pmd_ToF_Calibration_and Validation_Software_vx-y-z_20yy-mm-dd.exe"
 - Use existing installation path (e.g. C:\Program Files\pmdtechnologies_ag\pmd_Calibration_and_Validation_Software)
 and click on install button



Own modifications of a former version will be overwritten! Please save especially own implementation of the hash generation function!


Software download and installation (3)

- Wait until installation is finished (1).
- Close window (2).



Software download and installation (4)

Close information window.



You have now successfully installed/updated the pmd CALVADOS software.