Record Id shift/Machine 1/Mould-1/ Product-1-1			Start Time Machine Id 23/08/2014 11:40 Machine 1		Print By			Print Date 09/09/2014		
Code Mould		DG/Non-	DG Bu	G Bung		View L	.ine			
Product-1-1	Mould-1	0	YE	S	NO	YES				
Produ	ct Weigh	t (grams)		Cycle Time			Bore 1 Check			
Time	Weight	Pass	Time	•	Cycle		Time	Bore 1	Pass	
11:34	22.33	NO		Top D	:4:		15:31	2.33	NO(ssa)	
15:29	2.33	YES	T:	Tap Position				Bore 2 Check		
15:35	2.44	YES	Time	Tap	Pass					
15:41	23.33	YES	15:29	2	NO(,	Time	Bore 2	Pass	
15:42	24.22	YES		Buna	Check		15:31	2.33	NO(ssa)	
15:09	666.55	NO	Time	Bung	Pas	s		Neck Che	eck	
			15:31	Good	YES		Time	Neck	Pass	
							15:31	2.33	NO(ssa)	
	Wall 1	Thinkness '	Test				Quality	Check		
	Value			Pass			Value			
Time	15:2	29		Time			15:32			
Base	2.33	3	NO(ass)		Neck Round			Checked		
Closure	2.33	3	NO(ass)	NO(ass) Neck Complete		plete		NA		
Handle Bung 2.33		3	NO(ass)	NO(ass) Under The Handle				NA		
Handle Left 2.33		3	NO(ass) Bung If			illed Checked				
Handle Righ	lle Right 2.33		NO(ass)	NO(ass) Bung Base		е		Checked		
Under Hand		3	NO(ass)	` '		nght Of Dr	um	NA		
Staff	2.33	3	, ,		_	ithin Range		Yes		
					_	our/Texture		Checked		
					Staff			dsds		
				Δmbie	nt Test					
Time	Result 1	Result 2 Re	esult 3	Result 4	Result 5	Result 6	Result	7 Result 8	S Staff	
15:32	Pass	Pass Fa	ıil	Fail	Fail	Pass	Fail	Pass	NO(sd)	
				St	aff					
Supervisor 1 5			Technician 1			Operator 1				
Supervisor 2	2 6		Technician 2		3	Operator 2 7				
Supervisor 2					3	-				

Operator 3

Technician 3

Supervisor 3