Record Id shift/Machine 1/Mould-1/ Product-1-1			Start Time Machine Id 23/08/2014 11:40 Machine 1		Print By		<b>Print Date</b> 03/09/2014			
Code	Mould	DG/N	on-DG B	ung	Pierced View I		Line			
Product-1-1	Mould-1	0		ES	NO	YES				
Product Weight (grams)				Cvcle	e Time			Bore 1 Check		
Time	Weight	Pass	Time	, ,	Cycle		Time	Bore 1	Pass	
11:34	22.33	NO		T D	-		15:31	2.33	NO(ssa)	
15:29	2.33	YES		Tap Position				D 0 0	· · ·	
15:35	2.44	YES		CreatedTim∈ Tap Pass				Bore 2 Check		
15:41	23.33	YES	15:29	2	NO(	ddd)	Time	Bore 2	Pass	
15:42	24.22	YES		Bung Check			15:31	2.33	NO(ssa)	
15:09	666.55	NO	Time	Bung	Pas	s		Neck Ch	eck	
			15:31	Good	YES		Time	Neck	Pass	
							15:31	2.33	NO(ssa)	
	Wall 7	Thinknes:	L s Test				Quality	Check		
			Pass	Pass		Value				
Time	15::	29			Time			15:32		
Base	2.3	3	NO(ass	5)	Neck Rou	nd		Checked		
Closure	<b>e</b> 2.33		•	NO(ass)		Neck Complete		NA		
Handle Bun	Handle Bung 2.33		NO(ass	NO(ass)		Under The Handle		NA		
Handle Left 2.33		NO(ass)		Bung If Drilled			Checked			
Handle Right 2.33		3	NO(ass)		Bung Base			Checked		
Under Handle 2.33			NO(ass)			Bung Strenght Of Drum			NA	
Staff	2.3		`		_	ithin Rang		Yes		
					_	our/Textur		Checked		
					Staff			dsds		
				Δmhie	nt Test					
Time	Result 1	Result 2	Result 3	Result 4	Result 5	Result 6	Resul	t 7 Result	8 Staff	
	Pass	Pass	Fail	Fail	Fail	Pass	Fail	Pass	NO(sd)	
				St	aff					
Supervisor 1 5			Technician 1			Operator 1				
Supervisor 2 6		Technician 2		3	Operator					

Technician 3

Operator 3

Supervisor 3