

EDITS:

Cut trace between power switch and 5V line, making it only on/off.
DD and DR gpio pins are swapped?

FIXES NEEDED:

Audio amplifier doesn't boost enough for external speaker,
even with higher gain resistors