
0 procutting

steven Glasford 7-17-22



13,675" 1358" igive .25" give on all tubes

8.25 Sides med need to be cut

6.125 = 6 &

13.625 (13 &) Sides need to be cut

to 11.5 = 11 &

actually needs to be cut