Steven Kim Mr. Mason Adv Cisco CCNP P1,2 10/15/13

Lab 3 - Layer 2 Attacks

Purpose

The purpose of this lab was to learn how to execute attacks performed in Layer 2 and mitigate them. We were required to do a total of 3-4 attacks to ensure a thorough understanding of the attacks.

Background Information on Lab Concepts

Layer 2 attacks are attacks formed in the Data Link Layer in the OSI model. The Data Link Layer is responsible for transferring da0.ta between networks and detecting any errors occurring in the previous layer, the Physical Layer. It uses protocols like PPP, HDLC, and ADCCP for local area networks, and hardware addresses (also known as mac-addresses)

Hackers find a way to attack the network in this Data Link Layer. Examples include: CAM Table Overflow, DHCP Attacks, ARP Attacks, VLAN Hopping, Spanning Tree Attacks, CDP Attacks and etc. I've executed and mitigated four attacks in my lab: DHCP Starvation, CAM Table Overflow, CDP, and ARP Poisoning.

CAM Table Overflow is an attack that generates counterfeit MAC addresses until the number of MAC addresses reaches the maximum number permitted in a cam table, and floods a certain port of a Switch. The Switch has to broadcasts every traffic throughout the network to pass any other incoming traffic, just like a hub, disabling the Switch from storing any additional MAC addresses. This type of broadcast allows the hacker to view private information that the user doesn't want to reveal.

DHCP Starvation is an attack that exhausts the available addresses on a DHCP server and prevents the user from receiving any addresses from it. When this attack is executed, the user is disconnected from the network, not being able to receive a valid address and connect with other devices/users in the network.

ARP Poisoning (Spoofing) is an attack in which a hacker to send counterfeit ARP messages into networks. The attacker disrupts traffic by forwarding packets onto unwanted networks, causing the user to experience network disabilities.

CDP Attack, or Cisco Discovery Protocol Attack, is an attack that allows the hacker to cause Cisco devices to malfunction, including running out of memory and crashes. The attack can be executed when CDP is enabled.

The program I used was Backtrack 5 r3, a program run on VMware. It allows numerous attack commands, the one previously mentioned, to be performed. The *yersinia* –[alphabet] command can also be issued so that the attacker can go to various attacking modes.

Lab Summary

In this lab I used a simple network topology consisting of a Router, 1-2 Switches, and two hosts. The Router acted as a DHCP Server for DHCP Starvation. To set up DHCP, create a pool that requires a default-router id, a DNS server, and a network number.

CAM Table Overflow

After setting up backtrack (see below for commands), I attempted to initiate CAM Table Overflow . I proved this by using Wireshark in which the attacking host received ping packets from the victim hosts. I also went to the MAC address table and found that there were over 5000 dynamic addresses assigned on a single switchport.

The mitigation necessary for this attack was port-security; I had to set up port-security on all the ports to prevent the ports from being overflowed. The port-security commands allowed a single MAC address to be assigned per port. To ensure that the mitigation worked successfully, I again checked the number of MAC addresses assigned on a switchport and saw that only one address was assigned per switchport.

DHCP Starvation

To execute a DHCP Starvation attack, I first went to Yersinia (see commands below). I launched the attack that created a disruption in the DHCP Server; after verifying that IP addresses could not be assigned automatically using the commands *ipconfig* /release and *ipconfig* /renew, I realized that the attack was successful.

I found out that the mitigation necessary for this attack was the exact same as that for CAM Table Overflow. Switchport security initiated a shutdown on the port if a violation occurred and allowed only 1 address per port. This feature of port security allowed a detection and an action against the attack, which was necessary for the mitigation.

ARP Poisoning

For executing the ARP Poisoning Attack, I went to Ettercap (see commands below) and clicked scan for hosts. After that, I clicked Mitm then ARP Poisoning, then Sniff remote connections to execute the attack. I verified that the attack worked by using Wireshark, seeing that the false ARP packets were sent by the attacker and confusing the network. The victim host was then not able to ping and therefore communicate throughout the network.

For mitigation, I set up DHCP Snooping, which is a technique that allows only hosts with a specific address (IP or MAC) to have access to the network. This unique characteristic of DHCP Snooping kept sending denial messages, saying that it dropped ARP since there were no previous records of an IP address that has been used by a host.

CDP

To execute a CDP Attack, I went to Yersinia. I clicked the CDP tab and then simply the flood CDP table. This allowed a disruption in the CDP table, as verified by the command *show cdp entry* and/or *show cdp neighbors*. The attack host was also able to gain information that can be shown using the command *show cdp neighbors* on the victim host.

For mitigation, I simply disabled CDP on both the global config mode and the interface mode. CDP is a protocol that is enabled by default; I realized that turning this unnecessary protocol will ensure security and therefore mitigate the CDP attack executed by the attacking host.

Lab Commands

Setting up the topology did not require many commands: I created VLAN 2, grouped all ports to it, and set IP addresses to *interface vlan 2*, interface fa0/1, and hosts (for DHCP, I configured the pool). The commands required are *switchport mode access and switchport access vlan 2* on the interface mode. Before this, the command *vlan 2* had to be issued on the global config mode to create VLAN 2.

For DHCP Starvation setup, I issued the command *ip dhcp pool 1* on the global config mode to set up a DHCP pool. The commands network 10.0.0.0 255.255.255.0, dns-server 200.20.2.1, and default-router 10.0.0.1 were issued on the Router (config-dhcp)# mode.

To initiate Backtrack 5 rd3, I typed root for username and toor for the password. Then, I used the command *startx* to load the actual Backtrack applications.

The following are the commands for the attacks/mitigations:

1. CAM Table Overflow - Attack

I used the command macof - 1 eth1 in the Backtrack command prompt, which is where the first screen that came up after issuing the command startx. This shows a large list containing a vast amount of randomly generated MAC addresses.

2. CAM Table Overflow – Mitigation

The commands switchport port-security, switchport port-security maximum 1, switchport port-security mac-address sticky, and switchport port-security violation shutdown must be issued on the interface mode, on every interface. These commands enable Switchport Security against the attacks by allowing only 1 address per port, enabling sticky learning on the interfaces, and a shutdown of the interface when a violation is made.

3. DHCP Starvation – Attack

The command Yersinia –G must be issued to enter Yersinia. Then, click the Launch Attack tab and send DISCOVER packets. Verify that the attack was successful by issuing the command *ipconfig* /release and *ipconfig* /renew on the command prompt. The victim host should not be receiving any IP addresses from the DHCP Server; it should display an error message instead.

4. DHCP Starvation – Mitigation

The mitigation for DHCP Starvation, as mentioned earlier, is the same as that for CAM Table Overflow. Refer to the Mitigation commands in #2.

5. ARP Poisoning – Attack

There are a series of clicks needed for the ARP Poisoning Attack on Ettercap:

Before doing anything, verify that connectivity is ensured by clicking Scan for hosts on the top. Click Add to Target 1 or 2 to ensure that the Victim host is a target. Issue the command Ettercap —G to enter Ettercap mode. Click Mitm on the top then ARP Poisoning. Then, click Sniff remote connections to initiate the attack. Verify that the attack was successful by pinging and Wireshark. There will be a continuous loop on Wireshark while the victim host will receive *Destination Host Unreachable* messages.

6. ARP Poisoning – Mitigation

There were several commands that were needed to be issued for mitigating an ARP Poisoning Attack:

On the global config mode, type in the commands *ip dhcp snooping vlan 2, ip dhcp snooping, and ip arp inspection vlan 2*. As mentioned in the Lab Summary section, DHCP Snooping is a protocol that denies any unknown ARP requests. Then, on interface fa0/1 and fa0/3, issue the command *ip arp inspection trust*, which allows the Switch to trust an interface. Verify that the mitigation was successful by pinging the router.

7. CDP Attack - Attack


The command Yersinia –G must be issued initially. Then, click Launch Attack and then the CDP. Click Flood CDP table there and verify that the attack was successful through Wireshark on the attacking host and *show cdp entries* and *show cdp neighbors* on the global config mode of the victim host.

8. CDP Attack – Mitigation

The commands *no cdp run and no cdp enable* must be issued on the interface mode and the global config mode, respectively.

NOTE: All the mitigation commands were issued on the Switch.

Network Diagram with IPs



Configurations

DHCP Configuration before mitigation

Router 1

```
R1(config)#do sh run
                                               ip cef
Building configuration...
Current configuration: 1460 bytes
! Last configuration change at 15:28:05
                                               ip dhcp pool 1
UTC Thu Oct 10 2013
                                               network 10.0.0.0 255.255.255.0
version 15.1
                                                default-router 10.0.0.1
service timestamps debug datetime msec
                                                dns-server 200.20.2.1
service timestamps log datetime msec
no service password-encryption
                                               multilink bundle-name authenticated
!
hostname R1
boot-start-marker
                                               crypto pki token default removal
boot-end-marker
                                               timeout 0
                                               license udi pid CISCO2901/K9 sn
!
no aaa new-model
                                               FTX1704Y03B
memory-size iomem 10
                                               1
no ipv6 cef
ip source-route
```

```
ip forward-protocol nd
                                               no ip http server
                                               no ip http secure-server
interface Embedded-Service-Engine0/0
no ip address
shutdown
interface GigabitEthernet0/0
ip address 10.0.0.1 255.255.255.0
                                               control-plane
duplex auto
speed auto
interface GigabitEthernet0/1
                                               line con 0
no ip address
                                               line aux 0
shutdown
duplex auto
                                                no activation-character
speed auto
                                                no exec
                                                transport preferred none
interface Serial0/0/0
                                                transport input all
no ip address
                                                transport output pad telnet rlogin
                                               lapb-ta mop udptn v120 ssh
shutdown
                                                stopbits 1
no fair-queue
clock rate 2000000
                                               line vty 0 4
                                                login
interface Serial0/0/1
                                                transport input all
no ip address
shutdown
                                               scheduler allocate 20000 1000
clock rate 2000000
Switch 1
                                               !
S1(config)#do sh run
Building configuration...
                                               spanning-tree mode pvst
Current configuration: 2609 bytes
                                               spanning-tree etherchannel guard
!
                                               misconfig
version 12.2
                                               spanning-tree extend system-id
no service pad
service timestamps debug datetime msec
                                               vlan internal allocation policy
service timestamps log datetime msec
                                               ascending
no service password-encryption
!
hostname S1
1
boot-start-marker
                                               interface FastEthernet0/1
boot-end-marker
                                                switchport access vlan 2
                                                switchport mode access
!
                                               interface FastEthernet0/2
                                                switchport access vlan 2
no aaa new-model
                                                switchport mode access
system mtu routing 1500
authentication mac-move permit
                                               interface FastEthernet0/3
ip subnet-zero
                                                switchport access vlan 2
                                                switchport mode access
1
!
                                               interface Vlan1
                                                no ip address
```

```
shutdown
!
interface Vlan2
ip address 10.0.0.10 255.255.255.0
!
ip classless
ip http server
ip http secure-server
```

Other Configurations before mitigation

Router 1 (Server)

!

```
R1(config)#do sh run
Building configuration...
Current configuration : 1460 bytes
! Last configuration change at 15:28:05
UTC Thu Oct 10 2013
version 15.1
service timestamps debug datetime msec
service timestamps log datetime msec
no service password-encryption
!
hostname R1
1
boot-start-marker
boot-end-marker
!
no aaa new-model
memory-size iomem 10
no ipv6 cef
ip source-route
ip cef
multilink bundle-name authenticated
crypto pki token default removal
timeout 0
!
license udi pid CISCO2901/K9 sn
FTX1704Y03B
!
```

```
ip sla enable reaction-alerts
line con 0
line vty 5 15
end
interface Embedded-Service-Engine0/0
no ip address
shutdown
interface GigabitEthernet0/0
ip address 10.0.0.1 255.255.255.0
 duplex auto
 speed auto
interface GigabitEthernet0/1
no ip address
shutdown
duplex auto
speed auto
interface Serial0/0/0
no ip address
shutdown
no fair-queue
clock rate 2000000
interface Serial0/0/1
no ip address
shutdown
clock rate 2000000
ip forward-protocol nd
no ip http server
no ip http secure-server
control-plane
line con 0
line aux 0
line 2
no activation-character
 no exec
 transport preferred none
 transport input all
 transport output pad telnet rlogin
lapb-ta mop udptn v120 ssh
 stopbits 1
```

```
line vty 0 4
  login
  transport input all
!
scheduler allocate 20000 1000
```

Cam Table Overflow Mitigation (show run)

Switch 1

```
S1(config)#do sh run
Building configuration...
Current configuration: 2609 bytes
version 12.2
no service pad
service timestamps debug datetime msec
service timestamps log datetime msec
no service password-encryption
hostname S1
boot-start-marker
boot-end-marker
no aaa new-model
system mtu routing 1500
authentication mac-move permit
ip subnet-zero
spanning-tree mode pvst
spanning-tree etherchannel guard
misconfig
spanning-tree extend system-id
vlan internal allocation policy
ascending
interface FastEthernet0/1
switchport access vlan 2
switchport mode access
switchport port-security
switchport port-security mac-address
 switchport port-security mac-address
sticky acf2.c555.9788 vlan access
interface FastEthernet0/2
```

end

Switch 1

(Same as DHCP)

```
switchport access vlan 2
 switchport mode access
 switchport port-security
 switchport port-security mac-address
sticky
interface FastEthernet0/3
switchport access vlan 2
switchport mode access
switchport port-security
switchport port-security mac-address
sticky
interface Vlan1
no ip address
shutdown
interface Vlan2
 ip address 10.0.0.10 255.255.255.0
ip classless
ip http server
ip http secure-server
ip sla enable reaction-alerts
line con 0
line vty 5 15
1
end
S1(config)#do sh run
Building configuration...
Current configuration: 2609 bytes
version 12.2
no service pad
service timestamps debug datetime msec
service timestamps log datetime msec
no service password-encryption
hostname S1
boot-start-marker
boot-end-marker
no aaa new-model
system mtu routing 1500
authentication mac-move permit
ip subnet-zero
```

Switch 1 S1(config)#do sh run Building configuration... Current configuration: 2609 bytes spanning-tree mode pvst spanning-tree etherchannel guard version 12.2 misconfig no service pad spanning-tree extend system-id service timestamps debug datetime msec service timestamps log datetime msec vlan internal allocation policy no service password-encryption ascending hostname S1 boot-start-marker boot-end-marker interface FastEthernet0/1 switchport access vlan 2 switchport mode access switchport port-security switchport port-security mac-address no aaa new-model system mtu routing 1500 switchport port-security mac-address authentication mac-move permit sticky acf2.c555.9788 vlan access ip subnet-zero interface FastEthernet0/2 switchport access vlan 2 switchport mode access switchport port-security switchport port-security mac-address sticky interface FastEthernet0/3 spanning-tree mode pvst switchport access vlan 2 spanning-tree etherchannel guard switchport mode access misconfig switchport port-security spanning-tree extend system-id switchport port-security mac-address sticky vlan internal allocation policy ascending interface Vlan1 no ip address shutdown interface Vlan2 interface FastEthernet0/1 ip address 10.0.0.10 255.255.255.0 switchport access vlan 2 switchport mode access ip classless switchport port-security ip http server switchport port-security mac-address ip http secure-server sticky switchport port-security mac-address sticky acf2.c555.9788 vlan access ip sla enable reaction-alerts interface FastEthernet0/2 switchport access vlan 2 switchport mode access line con 0 switchport port-security line vty 5 15 switchport port-security mac-address ! sticky **DHCP Starvation Mitigation (show run)** interface FastEthernet0/3

switchport access vlan 2

```
switchport mode access
switchport port-security
switchport port-security mac-address
sticky
interface Vlan1
no ip address
shutdown
interface Vlan2
ip address 10.0.0.10 255.255.255.0
ip classless
ip http server
ip http secure-server
ip sla enable reaction-alerts
line con 0
line vty 5 15
end
```

ARP Poisoning Mitigation (show run)

Switch 1

```
S1(config)#do sh run
Building configuration...
Current configuration: 2609 bytes
version 12.2
no service pad
service timestamps debug datetime msec
service timestamps log datetime msec
no service password-encryption
!
hostname S1
!
boot-start-marker
boot-end-marker
!
no aaa new-model
system mtu routing 1500
authentication mac-move permit
ip subnet-zero
spanning-tree mode pvst
```

```
spanning-tree etherchannel guard
misconfig
spanning-tree extend system-id
vlan internal allocation policy
ascending
ip dhcp snooping vlan 2
ip dhcp snooping
ip arp inspection vlan 2
interface FastEthernet0/1
switchport access vlan 2
 switchport mode access
ip arp inspection trust
interface FastEthernet0/2
switchport access vlan 2
switchport mode access
interface FastEthernet0/3
switchport access vlan 2
switchport mode access
ip arp inspection trust
interface Vlan1
no ip address
shutdown
interface Vlan2
ip address 10.0.0.10 255.255.255.0
ip classless
ip http server
ip http secure-server
ip sla enable reaction-alerts
line con 0
line vty 5 15
```

CDP Attack Mitigation (show run)

Switch 1

```
S1(config) #do sh run
Building configuration...

Current configuration : 2609 bytes
!
version 12.2
no service pad
service timestamps debug datetime msec
service timestamps log datetime msec
no service password-encryption
```

```
hostname S1
boot-start-marker
boot-end-marker
1
no aaa new-model
system mtu routing 1500
authentication mac-move permit
ip subnet-zero
1
no cdp enable
no cdp run
spanning-tree mode pvst
spanning-tree etherchannel guard
misconfig
spanning-tree extend system-id
vlan internal allocation policy
ascending
interface FastEthernet0/1
switchport access vlan 2
```

```
switchport mode access
interface FastEthernet0/2
 switchport access vlan 2
switchport mode access
interface FastEthernet0/3
switchport access vlan 2
switchport mode access
interface Vlan1
no ip address
shutdown
interface Vlan2
 ip address 10.0.0.10 255.255.255.0
ip classless
ip http server
ip http secure-server
ip sla enable reaction-alerts
line con 0
line vty 5 15
end
```

Problems

Overall, I had 2 main problems in this lab: the burdensome research that was necessary for executing and mitigating the attacks and my inadequate planning for the video and the lab itself.

The research involved in this lab was tremendous and crucial. Since my peers and I did not have a clear background of Layer 2 Attacks, Mr. Mason required us to initially watch a video from a cisco website regarding Layer 2 Attacks. In addition to this video, I had to research every command that was not on the video; it was difficult to find how port security did not resolve every attacks that were performed. I also did not research enough information for performing and mitigating the attacks, such as not finding out which commands were necessary for initiating backtrack or not knowing which mitigation commands were appropriate.

My inadequate planning for the video also served as an impediment. Initially, I thought that I could hastily finish the video without practicing the filming beforehand. I was wrong: I could not finish the video for the very first attack after 2 hours. I did not realize how much time I would've saved had I not gone the vast amount of trial and errors. The process of filming that I

went through was done impromptu: I had only a vague sense of how to even perform the mitigations before filming a video. As time came, it became obvious that careful planning is another crucial factor for efficiency.

Conclusion

Although I had undergone numerous time-consuming processes throughout this lab, the overall result was satisfactory. I created a cisco video using Camtasia for the very first time. Not only that, I had the opportunity to familiarize myself with common Layer 2 attacks, a part of "hacking" that I've always been interested in, that are still prevalent in many network fields. Such familiarization includes learning how to defend my networking devices from future Layer 2 attacks, a skill that is crucial to network engineers.

For more information, check the following URL which is linked to the Video I created:

http://www.youtube.com/watch?v=Rh1P0MjxmbQ