

## Lean Management



Types of Waste

## Agenda

The Main Ones

Others



# DIGITAL

The Types of Waste

## **Transportation**

• **Definition:** Any movement of materials, supplies or resources that does not add value to the internal or external customer needs

- o Extra carts, fork lifts
- Multiple storage locations
- Complex inventory management
- Extra facility space
- Improper facility layout



## **Inventory**

• **Definition:** Any supply in excess to process requirements necessary to produce goods or services just in time

- Material between processes
- Additional material handling resources
- Additional investment / cost
- Storage space
- o Perishable, damage and obsolescence
- o LIFO instead of FIFO



## **Motion**

• **Definition:** Any movement of people, resources or machines which does not contribute/add value to the product or service

- o Human motion
- Lack of visual controls
- Looking for tools
- Material too far apart (walk time)
- o Machine motion



## Waiting

• **Definition:** Long period of inactivity for people, machine, or material waiting for each other

- o Improper scheduling
- o People waiting for machine or resources
- o Poor material planning
- o Late Deliveries
- Unbalanced operations



## **Over-Production**

 Definition: Producing faster or excess quantity than the internal or external customer needs

- Just-in-case reward system
- Large lot size batch processing
- o Improper demand planning/Unbalanced material flow
- Producing early
- Inventory stockpiles



## **Over-Processing**

• **Definition:** Effort which adds NO value to a product or service. Enhancements which are not valued by customers.

- Lack of clear customer specifications
- o Endless refinement
- o Redundant approvals
- o Extra copies or excessive information

## **Defect**

• **Definition:** Rework needed to rectify the defect in product or service to fulfill customer requirements

- Quality problems
- Extra resources to inspect/test/rework
- o Insufficient training
- o Inconsistent work methods, tools
- o Excessive variation

# DIGITAL PERATIONS

Other Types of Waste

## **Underutilized Skills**

- ✓ **Definition:** Any skill that is not utilized to its full potential leading to customer value
- **✓** Characteristics
  - Skills based compensation
  - Over qualification
  - Under performance
  - Morale

## **Wrong Use of Automation**

 Definition: Any automation that is taking longer than manual work or creating additional work

- Over automation
- Under automation
- Unnecessary automation
- Automation defects/rejects
- Examples



## **Wrong Use of Metrics**

• **Definition:** Any metrics that is incorrectly measured, inappropriately used or misinterpreted is another type of waste

- o Incorrect data collection
- o Inappropriate use
- o Misinterpretation
- Misaligned targets or goals
- o Examples



## **Summary**

Seven Main Types of Waste

Other Types of Waste



# DIGITAL



Knowledge Check

•

Which of the following is not one of the seven wastes?

- A. Overproduction
- B. Transporting
- C. Excess machine capacity
- D. Waiting



Which of the following is not one of the seven wastes?

- A. Overproduction
- B. Transporting
- C. Excess machine capacity
- D. Waiting



The correct answer is **C** 

The main seven types of waste do not include excess machine capacity. While it is in some form of potential waste of resource, but it is not part of the seven main waste types.



2

## What are the main seven types of waste?

- A. Transportation, inventory, motion, waiting, over-production, over-processing, defects
- B. Money, software, entertainment, waiting, resources, under-utilized machines, excess machine capacity
- C. Inventory, storage, misalignment, overheating, electricity, chatting, communication
- D. Transportation, inventory, motion, waiting, underutilized money, over-processing, communication



2

### What are the main seven types of waste?

- A. Transportation, inventory, motion, waiting, over-production, over-processing, defects
- B. Money, software, entertainment, waiting, resources, under-utilized machines, excess machine capacity
- C. Inventory, storage, misalignment, overheating, electricity, chatting, communication
- D. Transportation, inventory, motion, waiting, underutilized money, over-processing, communication



#### The correct answer is A

The main seven types of waste are Transportation, inventory, motion, waiting, over-production, over-processing, defects.

