


If zones overlap here, the power-vs-PPFD gap is calibration; if not, it's hardware

Power vs drive — same actuator axis



Current vs drive

