BACKFLOW PREVENTION ASSEMBLY TEST REPORT

WATER PURVEYOR City of Mercer Island ACCOUNT #

ASSEMBLY ID/FILE #/UTILITY DEVICE #/ID Meter #

NAME OF PREMISE Legacy Apts Commercial ■ Residential ☐

SERVICE ADDRESS 2605 76th Ave SE CITY Mercer Island ZIP 98040

CONTACT PERSON PHONE

LOCATION OF ASSEMBLY Sprinkler Riser Room

DOWNSTREAM PROCESS Domestic Water Bypass DCVA ☐ RPBA ■ PVBA ☐ OTHER

NEW INSTALL ■ EXISTING ☐ REPLACEMENT ☐ OLD SER. #

WASHINGTON STATE APPROVED ASSEMBLY? YES ■ NO ☐ PROPER INSTALLATION? YES ■ NO ☐

MAKE OF ASSEMBLY Watts MODEL LF009M2QT SERIAL NO. 046484 SIZE 2"

	DCVA / RPBA CHECK VALVE NO.1	DCVA / RPBA CHECK VALVE NO.2	RPBA	PVBA/SVBA AIR INLET
INITIAL TEST PASSED ■ FAILED ☐	LEAKED ☐ CLOSED TIGHT ☐ PSID Min 1.0	LEAKED ☐ CLOSED TIGHT ■ PSID Min 1.0	OPENED AT 4.4 PSID Min 2.0 #1 CHECK 10.2 PSID Min 5.0 AIR GAP OK? Yes	OPENED AT PSID Min 1.0 DID NOT OPEN ☐
NEW PARTS AND REPAIRS	CLEAN REPLACE PART ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐	CLEAN REPLACE PART ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐	CLEAN REPLACE PART ☐ ☐ Diaphragm ☐ ☐ RV Disc ☐ ☐ ☐ ☐ ☐ ☐ Exercised Relief Valve ☐	CHECK VALVE HELD AT PSID Min 1.0 LEAKED ☐ CLEANED ☐ REPAIRED ☐
TEST AFTER REPAIRS PASSED ☐ FAILED ☐	LEAKED ☐ CLOSED TIGHT ☐ PSID Min 1.0	LEAKED ☐ CLOSED TIGHT ☐ PSID Min 1.0	OPENED AT PSID Min 2.0 #1 CHECK PSID Min 5.0	AIR INLET PSID Min 1.0 CHK VALVE PSID Min 1.0

AIR GAP INSPECTION: Supply Pipe Diameter: Separation: Pass ☐ Fail ☐ Detector Meter Reading

REMARKS: Used USC 10th Edition Field Test Procedures. Permit #1501-205

LINE PRESSURE 75 PSI CONFINED SPACE? NO

TESTER'S SIGNATURE: Ron Brown CERT. NO. B4203 DATE 4/6/2016

TESTER'S NAME PRINTED: Ron Brown TESTER'S PHONE # (206)-226-8019 (425) 821-6801

REPAIRED BY: DATE

FINAL TEST BY: CERT. NO. B4203 DATE

CALIBRATION DATE 6/1/15 GAUGE # D1130060 Mid-West 845-5 ■

CALIBRATION DATE 10/5/15 GAUGE # 8815 Prime 246 ☐ SERVICE RESTORED? YES ■ NO ☐

LEFT SERVICE AS FOUND–Meter/Isolation valve: Open ☐ Closed ☐ SOV#1: Open ☐ Closed ☐ SOV#2: Open ☐ Closed ☐

I certify that this report is accurate, and I have used WAC 246-290-490 approved test methods and test equipment.

R A Brown Backflow Testing
14213 95th AVE NE
Kirkland, WA 98034-5152

rabrownbft@yahoo.com
Backflow Specialty Plumber License #
BROWNR*954B8

Ron Brown
Home/ Fax: 425-821-6801
Cell: 206-226-8019

BACKFLOW PREVENTION ASSEMBLY TEST REPORT

WATER PURVEYOR City of Mercer Island ACCOUNT #

ASSEMBLY ID/FILE #/UTILITY DEVICE #/ID Meter #

NAME OF PREMISE Legacy Apts Commercial ■ Residential ☐

SERVICE ADDRESS 2605 76th Ave SE CITY Mercer Island ZIP 98040

CONTACT PERSON PHONE

LOCATION OF ASSEMBLY Sprinkler Riser Room

DOWNSTREAM PROCESS Domestic Water DCVA ☐ RPBA ■ PVBA ☐ OTHER

NEW INSTALL ■ EXISTING ☐ REPLACEMENT ☐ OLD SER. #

WASHINGTON STATE APPROVED ASSEMBLY? YES ■ NO ☐ PROPER INSTALLATION? YES ■ NO ☐

MAKE OF ASSEMBLY Watts MODEL 957 SERIAL NO. PC-2934 SIZE 4"

	DCVA / RPBA CHECK VALVE NO.1	DCVA / RPBA CHECK VALVE NO.2	RPBA	PVBA/SVBA AIR INLET
INITIAL TEST PASSED ■ FAILED ☐	LEAKED ☐ CLOSED TIGHT ☐ _____ PSID Min 1.0	LEAKED ☐ CLOSED TIGHT ■ _____ PSID Min 1.0	OPENED AT 2.9 PSID Min 2.0 #1 CHECK 9.2 PSID Min 5.0 AIR GAP OK? Yes	OPENED AT _____ PSID Min 1.0 DID NOT OPEN ☐ CHECK VALVE HELD AT _____ PSID Min 1.0 LEAKED ☐
NEW PARTS AND REPAIRS	CLEAN REPLACE PART ☐ ☐ _____ ☐ ☐ _____ ☐ ☐ _____ ☐ ☐ _____ ☐ ☐ _____	CLEAN REPLACE PART ☐ ☐ _____ ☐ ☐ _____ ☐ ☐ _____ ☐ ☐ _____ ☐ ☐ _____	CLEAN REPLACE PART ☐ ☐ Diaphragm ☐ ☐ RV Disc ☐ ☐ _____ ☐ ☐ _____ ☐ ☐ _____ Exercised Relief Valve ☐	CLEANED ☐ REPAIRED ☐
TEST AFTER REPAIRS PASSED ☐ FAILED ☐	LEAKED ☐ CLOSED TIGHT ☐ _____ PSID Min 1.0	LEAKED ☐ CLOSED TIGHT ☐ _____ PSID Min 1.0	OPENED AT _____ PSID Min 2.0 #1 CHECK _____ PSID Min 5.0	AIR INLET _____ PSID Min 1.0 CHK VALVE _____ PSID Min 1.0

AIR GAP INSPECTION: Supply Pipe Diameter:_____ Separation:_____ Pass ☐ Fail ☐ Detector Meter Reading

REMARKS: Used USC 10th Edition Field Test Procedures. Permit # 1501-205

LINE PRESSURE 75 PSI CONFINED SPACE? No

TESTER'S SIGNATURE: Ron Brown CERT. NO. B4203 DATE 4/6/2016

TESTER'S NAME PRINTED: Ron Brown TESTER'S PHONE # (206)-226-8019 (425) 821-6801

REPAIRED BY: DATE

FINAL TEST BY: CERT. NO. B4203 DATE

CALIBRATION DATE 6/1/15 GAUGE #01130060 Mid-West 845-5 ■

CALIBRATION DATE 10/5/15 GAUGE # 8815 Prime 246 ☐

SERVICE RESTORED? YES ■ NO ☐

LEFT SERVICE AS FOUND–Meter/Isolation valve: Open ☐ Closed ☐ SOV#1: Open ☐ Closed ☐ SOV#2: Open ☐ Closed ☐

I certify that this report is accurate, and I have used WAC 246-290-490 approved test methods and test equipment.

R A Brown Backflow Testing
14213 95th AVE NE
Kirkland, WA 98034-5152

rabrownbft@yahoo.com
Backflow Specialty Plumber License #
BROWNR*954B8

Ron Brown
Home/ Fax: 425-821-6801
Cell: 206-226-8019

BACKFLOW PREVENTION ASSEMBLY TEST REPORT

WATER PURVEYOR City of Mercer Island ACCOUNT #

ASSEMBLY ID/FILE #/UTILITY DEVICE #/ID Meter #

NAME OF PREMISE Legacy Apts Commercial ■ Residential ☐

SERVICE ADDRESS 2605 76th Ave SE CITY Mercer Island ZIP 98040

CONTACT PERSON PHONE

LOCATION OF ASSEMBLY Sprinkler Riser Room

DOWNSTREAM PROCESS Retail Water DCVA ☐ RPBA ■ PVBA ☐ OTHER

NEW INSTALL ■ EXISTING ☐ REPLACEMENT ☐ OLD SER. #

WASHINGTON STATE APPROVED ASSEMBLY? YES ■ NO ☐ PROPER INSTALLATION? YES ■ NO ☐

MAKE OF ASSEMBLY Watts MODEL 957 SERIAL NO. QA-0624 SIZE 3"

	DCVA / RPBA CHECK VALVE NO.1	DCVA / RPBA CHECK VALVE NO.2	RPBA	PVBA/SVBA AIR INLET
INITIAL TEST PASSED ☐ FAILED ■	LEAKED ■ CLOSED TIGHT ☐ PSID Min 1.0	LEAKED ☐ CLOSED TIGHT ☐ PSID Min 1.0	OPENED AT 3.6 PSID Min 2.0 #1 CHECK 4.6 PSID Min 5.0 AIR GAP OK? Yes	OPENED AT PSID Min 1.0 DID NOT OPEN ☐ CHECK VALVE HELD AT PSID Min 1.0 LEAKED ☐
NEW PARTS AND REPAIRS	CLEAN REPLACE PART ■ ☐ Disc ■ ☐ Seat ☐ ☐ ☐ ☐ ☐ ☐	CLEAN REPLACE PART ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐	CLEAN REPLACE PART ☐ ☐ Diaphragm ☐ ☐ RV Disc ☐ ☐ ☐ ☐ ☐ ☐ Exercised Relief Valve ☐	CLEANED ☐ REPAIRED ☐
TEST AFTER REPAIRS PASSED ■ FAILED ☐	LEAKED ☐ CLOSED TIGHT ☐ PSID Min 1.0	LEAKED ☐ CLOSED TIGHT ■ PSID Min 1.0	OPENED AT 3.8 PSID Min 2.0 #1 CHECK 7.4 PSID Min 5.0	AIR INLET PSID Min 1.0 CHK VALVE PSID Min 1.0

AIR GAP INSPECTION: Supply Pipe Diameter: Separation: Pass ☐ Fail ☐ Detector Meter Reading

REMARKS: Used USC 10th Edition Field Test Procedures. Permit # 1501-205

LINE PRESSURE 75 PSI CONFINED SPACE? NO

TESTER'S SIGNATURE: Ron Brown CERT. NO. B4203 DATE 4/6/2016

TESTER'S NAME PRINTED: Ron Brown TESTER'S PHONE # (206)-226-8019 (425) 821-6801

REPAIRED BY: Ron Brown DATE 4/6/2016

FINAL TEST BY: Ron Brown CERT. NO. B4203 DATE 4/6/2016

CALIBRATION DATE 6/1/15 GAUGE # 01130060 Mid-West 845-5 ■

CALIBRATION DATE 10/5/15 GAUGE # 8815 Prime 246 ☐ SERVICE RESTORED? YES ■ NO ☐

LEFT SERVICE AS FOUND–Meter/Isolation valve: Open ☐ Closed ☐ SOV#1: Open ☐ Closed ☐ SOV#2: Open ☐ Closed ☐

I certify that this report is accurate, and I have used WAC 246-290-490 approved test methods and test equipment.

R A Brown Backflow Testing
14213 95th AVE NE
Kirkland, WA 98034-5152

rabrownbft@yahoo.com
Backflow Specialty Plumber License #
BROWNR*954B8

Ron Brown
Home/ Fax: 425-821-6801
Cell: 206-226-8019

BACKFLOW PREVENTION ASSEMBLY TEST REPORT

WATER PURVEYOR City of Mercer Island ACCOUNT #

ASSEMBLY ID/FILE #/UTILITY DEVICE #/ID Meter #

NAME OF PREMISE Legacy Apts Commercial ■ Residential ☐

SERVICE ADDRESS 2605 76th Ave SE CITY Mercer Island ZIP 98040

CONTACT PERSON PHONE

LOCATION OF ASSEMBLY Trash room on P level

DOWNSTREAM PROCESS Trash Chute DCVA ☐ RPBA ■ PVBA ☐ OTHER

NEW INSTALL ■ EXISTING ☐ REPLACEMENT ☐ OLD SER. #

WASHINGTON STATE APPROVED ASSEMBLY? YES ■ NO ☐ PROPER INSTALLATION? YES ■ NO ☐

MAKE OF ASSEMBLY Watts MODEL LF009QT SERIAL NO. 23374 SIZE 5"

	DCVA / RPBA CHECK VALVE NO.1	DCVA / RPBA CHECK VALVE NO.2	RPBA	PVBA/SVBA AIR INLET
INITIAL TEST PASSED ☐ FAILED ■	LEAKED ☐ CLOSED TIGHT ☐ PSID (Min 1.0)	LEAKED ☐ CLOSED TIGHT ☐ PSID (Min 1.0)	OPENED AT PSID (Min 2.0) #1 CHECK PSID (Min 5.0) AIR GAP OK? Yes	OPENED AT PSID (Min 1.0) DID NOT OPEN ☐ CHECK VALVE HELD AT PSID (Min 1.0) LEAKED ☐ CLEANED ☐ REPAIRED ☐
NEW PARTS AND REPAIRS	CLEAN REPLACE PART ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐	CLEAN REPLACE PART ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐	CLEAN REPLACE PART ■ ☐ Diaphragm ☐ ☐ RV Disc ■ ☐ Seat ■ ☐ Stem ☐ ☐ Exercised Relief Valve ☐	
TEST AFTER REPAIRS PASSED ■ FAILED ☐	LEAKED ☐ CLOSED TIGHT ☐ PSID (Min 1.0)	LEAKED ☐ CLOSED TIGHT ■ PSID (Min 1.0)	OPENED AT 3.4 PSID (Min 2.0) #1 CHECK 6.6 PSID (Min 5.0)	AIR INLET PSID (Min 1.0) CHK VALVE PSID (Min 1.0)

AIR GAP INSPECTION: Supply Pipe Diameter: Separation: Pass ☐ Fail ☐ Detector Meter Reading

REMARKS: Used USC 10th Edition Field Test Procedures. Permit #1501-205, water oozing out top of cover through air vent. LINE PRESSURE 60 PSI CONFINED SPACE? no

TESTER'S SIGNATURE: Ron Brown CERT. NO. B4203 DATE 4/6/2016

TESTER'S NAME PRINTED: Ron Brown TESTER'S PHONE # (206)-226-8019 (425) 821-6801

REPAIRED BY: Ron Brown DATE 4/6/2016

FINAL TEST BY: Ron Brown CERT. NO. B4203 DATE 4/6/2016

CALIBRATION DATE 6/1/15 GAUGE #01130060 Mid-West 845-5 ☐

CALIBRATION DATE 10/5/15 GAUGE # 8815 Prime 246 ☐ SERVICE RESTORED? YES ☐ NO ☐

LEFT SERVICE AS FOUND–Meter/Isolation valve: Open ☐ Closed ☐ SOV#1: Open ☐ Closed ☐ SOV#2: Open ☐ Closed ☐

I certify that this report is accurate, and I have used WAC 246-290-490 approved test methods and test equipment.

R A Brown Backflow Testing
14213 95th AVE NE
Kirkland, WA 98034-5152

rabrownbft@yahoo.com
Backflow Specialty Plumber License #
BROWNR*954B8

Ron Brown
Home/ Fax: 425-821-6801
Cell: 206-226-8019