

OOS18000G — 0001HR2B

Captured from
Syn918p
on 2026-10-05 15:32 UTC. SMART interface:
`smartctl -a -d sat /dev/sdb`
.

Drive identity and condition

Field	Captured value
Model	OOS18000G
Serial	0001HR2B
Capacity	18,000,207,937,536 bytes (18.0 TB)
Rotation	7,200 rpm
Power-on hours	4,433
SMART overall	PASSED
Known condition	Operator reports this drive started failing immediately after insertion; treat as failing regardless of the SMART overall summary
ATA errors / UDMA CRC errors / command timeouts	155 / 127 / 2
Reallocated / pending / offline uncorrectable	0 / 0 / 0
Temperature at capture	36 °C (min/max 35/39 °C)

Full SMART report

smartctl 6.5 (build date Mar 2 2021) [x86_64-linux-4.4.59+] (local build)
Copyright (C) 2002-16, Bruce Allen, Christian Franke, www.smartmontools.org



=== START OF INFORMATION SECTION ===

Device Model: OOS18000G
Serial Number: 0001HR2B
LU WWN Device Id: 5 000c50 0db0de5e5
Firmware Version: 00S1
User Capacity: 18,000,207,937,536 bytes [18.0 TB]
Sector Sizes: 512 bytes logical, 4096 bytes physical
Rotation Rate: 7200 rpm
Form Factor: 3.5 inches
Device is: Not in smartctl database [for details use: -P showall]
ATA Version is: Unknown(0x0fe0) (minor revision not indicated)
SATA Version is: SATA >3.2 (0x1ff), 6.0 Gb/s (current: 6.0 Gb/s)
Local Time is: Mon Oct 5 10:32:41 2026 -05
SMART support is: Available - device has SMART capability.
SMART support is: Enabled

=== START OF READ SMART DATA SECTION ===

SMART overall-health self-assessment test result: PASSED

General SMART Values:

Offline data collection status: (0x82) Offline data collection activity
was completed without error.

Auto Offline Data Collection: Enabled.

Self-test execution status: (0) The previous self-test routine completed
without error or no self-test has ever
been run.

Total time to complete Offline
data collection: (559) seconds.

Offline data collection
capabilities: (0x7b) SMART execute Offline immediate.
Auto Offline Data Collection on/off support.
Suspend Offline collection upon new
command.
Offline surface scan supported.

Self-test supported.
 Conveyance Self-test supported.
 Selective Self-test supported.
 SMART capabilities: (0x0003) Saves SMART data before entering
 power-saving mode.
 Supports SMART auto save timer.
 Error logging capability: (0x01) Error logging supported.
 General Purpose Logging supported.
 Short self-test routine
 recommended polling time: (1) minutes.
 Extended self-test routine
 recommended polling time: (1537) minutes.
 Conveyance self-test routine
 recommended polling time: (2) minutes.
 SCT capabilities: (0x70bd) SCT Status supported.
 SCT Error Recovery Control supported.
 SCT Feature Control supported.
 SCT Data Table supported.

SMART Attributes Data Structure revision number: 10

Vendor Specific SMART Attributes with Thresholds:

ID#	ATTRIBUTE_NAME	FLAG	VALUE	WORST	THRESH	TYPE	UPDATED	
WHEN_FAILED	RAW_VALUE							
1	Raw_Read_Error_Rate	0x000f	083	065	044	Pre-fail	Always	-
178856831								
3	Spin_Up_Time	0x0003	090	090	000	Pre-fail	Always	-
0								
4	Start_Stop_Count	0x0032	100	100	020	Old_age	Always	-
71								
5	Reallocated_Sector_Ct	0x0033	100	100	010	Pre-fail	Always	-
0								
7	Seek_Error_Rate	0x000f	079	061	045	Pre-fail	Always	-
72100457								
9	Power_On_Hours	0x0032	095	095	000	Old_age	Always	-
4433								
10	Spin_Retry_Count	0x0013	100	100	097	Pre-fail	Always	-
0								
12	Power_Cycle_Count	0x0032	100	100	020	Old_age	Always	-
51								
18	Unknown_Attribute	0x000b	100	100	050	Pre-fail	Always	-

0								
187	Reported_Uncorrect	0x0032	100	100	000	Old_age	Always	-
0								
188	Command_Timeout	0x0032	100	099	000	Old_age	Always	-
2								
190	Airflow_Temperature_Cel	0x0022	064	041	000	Old_age	Always	-
36	(Min/Max 35/39)							
192	Power-Off_Retract_Count	0x0032	100	100	000	Old_age	Always	-
41								
193	Load_Cycle_Count	0x0032	100	100	000	Old_age	Always	-
1484								
194	Temperature_Celsius	0x0022	036	059	000	Old_age	Always	-
36	(0 16 0 0 0)							
197	Current_Pending_Sector	0x0012	100	100	000	Old_age	Always	-
0								
198	Offline_Uncorrectable	0x0010	100	100	000	Old_age	Offline	-
0								
199	UDMA_CRC_Error_Count	0x003e	200	164	000	Old_age	Always	-
127								
200	Multi_Zone_Error_Rate	0x0023	100	100	001	Pre-fail	Always	-
0								
240	Head_Flying_Hours	0x0000	100	100	000	Old_age	Offline	-
211	(209 232 0)							
241	Total_LBAs_Written	0x0000	100	253	000	Old_age	Offline	-
131358349017								
242	Total_LBAs_Read	0x0000	100	253	000	Old_age	Offline	-
113892978183								

SMART Error Log Version: 1

ATA Error Count: 155 (device log contains only the most recent five errors)

CR = Command Register [HEX]

FR = Features Register [HEX]

SC = Sector Count Register [HEX]

SN = Sector Number Register [HEX]

CL = Cylinder Low Register [HEX]

CH = Cylinder High Register [HEX]

DH = Device/Head Register [HEX]

DC = Device Command Register [HEX]

ER = Error register [HEX]

ST = Status register [HEX]

Powered_Up_Time is measured from power on, and printed as
DDd+hh:mm:SS.sss where DD=days, hh=hours, mm=minutes,
SS=sec, and sss=millisec. It "wraps" after 49.710 days.

Error 155 occurred at disk power-on lifetime: 301 hours (12 days + 13 hours)
When the command that caused the error occurred, the device was active or idle.

After command completion occurred, the registers were:

ER ST SC SN CL CH DH

-- -- -- -- --

40 51 00 00 00 00 00 Error: UNC at LBA = 0x00000000 = 0

Commands leading to the error were:

CR	FR	SC	SN	CL	CH	DH	DC	Powered_Up_Time	Command/Feature_Name
--	--	--	--	--	--	--	--	-----	-----
60	00	e0	ff	ff	ff	4f	00	02:11:02.165	READ FPDMA QUEUED
60	00	e0	20	0a	00	40	00	02:11:02.165	READ FPDMA QUEUED
60	00	e0	20	02	00	40	00	02:11:02.163	READ FPDMA QUEUED
2f	00	01	10	00	00	00	00	02:11:02.084	READ LOG EXT
60	00	e0	20	08	00	40	00	02:11:02.038	READ FPDMA QUEUED

Error 154 occurred at disk power-on lifetime: 301 hours (12 days + 13 hours)
When the command that caused the error occurred, the device was active or idle.

After command completion occurred, the registers were:

ER ST SC SN CL CH DH

-- -- -- -- --

40 51 00 00 00 00 00 Error: UNC at LBA = 0x00000000 = 0

Commands leading to the error were:

CR	FR	SC	SN	CL	CH	DH	DC	Powered_Up_Time	Command/Feature_Name
--	--	--	--	--	--	--	--	-----	-----
60	00	e0	20	08	00	40	00	02:11:02.038	READ FPDMA QUEUED
60	00	e0	20	00	00	40	00	02:11:02.037	READ FPDMA QUEUED
2f	00	01	e0	00	00	00	00	02:10:15.447	READ LOG EXT
b0	da	00	00	4f	c2	00	00	02:10:15.447	SMART RETURN STATUS
60	00	e0	ff	ff	ff	4f	00	02:09:56.700	READ FPDMA QUEUED

Error 153 occurred at disk power-on lifetime: 301 hours (12 days + 13 hours)
When the command that caused the error occurred, the device was active or idle.

After command completion occurred, the registers were:

ER ST SC SN CL CH DH

-- -- -- -- --

40 51 00 00 00 00 00 Error: UNC at LBA = 0x00000000 = 0

Commands leading to the error were:

CR	FR	SC	SN	CL	CH	DH	DC	Powered_Up_Time	Command/Feature_Name
----	----	----	----	----	----	----	----	-----------------	----------------------

-- -- -- -- --

60	00	e0	20	0a	00	40	00	02:09:56.583	READ FPDMA QUEUED
----	----	----	----	----	----	----	----	--------------	-------------------

60	00	e0	ff	ff	ff	4f	00	02:09:56.583	READ FPDMA QUEUED
----	----	----	----	----	----	----	----	--------------	-------------------

60	00	e0	20	02	00	40	00	02:09:56.582	READ FPDMA QUEUED
----	----	----	----	----	----	----	----	--------------	-------------------

2f	00	01	10	00	00	00	00	02:09:56.225	READ LOG EXT
----	----	----	----	----	----	----	----	--------------	--------------

60	00	e0	20	08	00	40	00	02:09:56.178	READ FPDMA QUEUED
----	----	----	----	----	----	----	----	--------------	-------------------

Error 152 occurred at disk power-on lifetime: 301 hours (12 days + 13 hours)

When the command that caused the error occurred, the device was active or idle.

After command completion occurred, the registers were:

ER ST SC SN CL CH DH

-- -- -- -- --

40 51 00 00 00 00 00 Error: UNC at LBA = 0x00000000 = 0

Commands leading to the error were:

CR	FR	SC	SN	CL	CH	DH	DC	Powered_Up_Time	Command/Feature_Name
----	----	----	----	----	----	----	----	-----------------	----------------------

-- -- -- -- --

60	00	e0	20	08	00	40	00	02:09:56.178	READ FPDMA QUEUED
----	----	----	----	----	----	----	----	--------------	-------------------

60	00	e0	20	00	00	40	00	02:09:56.178	READ FPDMA QUEUED
----	----	----	----	----	----	----	----	--------------	-------------------

b0	d5	01	01	4f	c2	00	00	02:03:16.959	SMART READ LOG
----	----	----	----	----	----	----	----	--------------	----------------

b0	d5	01	06	4f	c2	00	00	02:03:16.873	SMART READ LOG
----	----	----	----	----	----	----	----	--------------	----------------

b0	d0	01	00	4f	c2	00	00	02:03:16.869	SMART READ DATA
----	----	----	----	----	----	----	----	--------------	-----------------

Error 151 occurred at disk power-on lifetime: 301 hours (12 days + 13 hours)

When the command that caused the error occurred, the device was active or idle.

After command completion occurred, the registers were:

ER ST SC SN CL CH DH

-- -- -- -- --

40 51 00 00 00 00 00 Error: UNC at LBA = 0x00000000 = 0

Commands leading to the error were:

CR	FR	SC	SN	CL	CH	DH	DC	Powered_Up_Time	Command/Feature_Name
60	00	08	00	08	00	40	00	02:01:38.452	READ FPDMA QUEUED
2f	00	01	10	00	00	00	00	02:01:38.343	READ LOG EXT
60	00	08	00	08	00	40	00	02:01:38.295	READ FPDMA QUEUED
60	00	08	ff	ff	ff	4f	00	02:01:38.295	READ FPDMA QUEUED
60	00	08	ff	ff	ff	4f	00	02:01:38.294	READ FPDMA QUEUED

SMART Self-test log structure revision number 1

Num	Test_Description	Status	Remaining	LifeTime(hours)	LBA_of_first_error
# 1	Short offline	Completed without error	00%	4230	-
# 2	Short offline	Completed without error	00%	3487	-
# 3	Short offline	Completed without error	00%	2744	-
# 4	Short offline	Completed without error	00%	2025	-
# 5	Short offline	Completed without error	00%	1282	-
# 6	Short offline	Completed without error	00%	952	-
# 7	Short offline	Completed without error	00%	0	-

SMART Selective self-test log data structure revision number 1

SPAN	MIN_LBA	MAX_LBA	CURRENT_TEST_STATUS
1	0	0	Not_testing
2	0	0	Not_testing
3	0	0	Not_testing
4	0	0	Not_testing
5	0	0	Not_testing

Selective self-test flags (0x0):

After scanning selected spans, do NOT read-scan remainder of disk.

If Selective self-test is pending on power-up, resume after 0 minute delay.