

### Figure 5: Confusion Matrix (Limb Leads)

		Predicted	
		Swap Detected	No Swap Detected
Actual	Swap	TP 85	FN 323
	No Swap	FP 4	TN 132