UAT Riverbend Honda

Dealer service repair order

RO UAT-P40-068-RO2 | August 15, 2025

TEST FIXTURE - fictional transaction and specimen terms, not an official manufacturer publication.

Vehicle and visit

Vehicle	2025 Honda CR-V EX-L | VIN 1UATHRW50S0000068
Customer	UAT Sample Buyer
Advisor / tech	UAT Service Advisor B / Tech 07
RO open / close	2025-08-15 / 2025-08-15
Odometer in / out	9,800 miles / 9,801 miles
Concern	Oil service and 10,000-mile inspection

Labor and parts - USD

Description	Amount
Engine oil and filter change (0W-20 synthetic)	$79.95
Cabin air filter replacement	$48.00
10,000-mile multi-point inspection	$0.00
Shop supplies / environmental	$6.05
Sales tax	$8.04
CUSTOMER PAY TOTAL	$142.04
Warranty / manufacturer pay	$0.00

Service notes

Inspection notes: brakes, tires, fluids and underbody OK. No powertrain concern found.

Next oil service due at 14,800 miles or 2026-02-15. This visit is customer-pay maintenance, not a warranty claim.

Customer / advisor acknowledgement

Buyer: _____ Dealer / seller: _____

Printed name: UAT Sample Buyer Date: as shown above