UAT Riverbend Honda

Dealer warranty repair order

RO UAT-P40-068-RO4 | September 12, 2026

TEST FIXTURE - fictional transaction and specimen terms, not an official manufacturer publication.

Vehicle and visit

Vehicle	2025 Honda CR-V EX-L | VIN 1UATHRW50S0000068
Customer	UAT Sample Buyer
Advisor / tech	UAT Service Advisor C / Tech 03
RO open / close	2026-09-12 / 2026-09-12
Odometer in / out	20,800 miles / 20,802 miles
Concern	Coolant seepage at water pump; diagnose and repair under warranty
Authorization	Manufacturer warranty claim UAT-WC-068-WP | Approved

Labor and parts - USD

Description	Amount
Diagnose coolant seepage (warranty)	$0.00 customer / $145.00 warranty
Replace water pump assembly (OEM) (warranty)	$0.00 customer / $385.00 warranty
Coolant refill and bleed (warranty)	$0.00 customer / $62.00 warranty
Shop supplies (warranty)	$0.00 customer / $12.00 warranty
CUSTOMER PAY TOTAL	$0.00
WARRANTY / MANUFACTURER PAY TOTAL	$604.00

Service notes

Covered powertrain / cooling component repair under the Honda new-vehicle powertrain limited warranty (S68-02). Deductible $0. Customer pay $0.00.

Parts and labor paid by manufacturer. Keep this RO with the warranty schedule as proof of covered-part maintenance and repair. Warranty clocks are not restarted.

Customer / advisor acknowledgement

Buyer: _____ Dealer / seller: _____

Printed name: UAT Sample Buyer Date: as shown above