Granite Ridge Ford

2400 Example Turnpike, Testville, ME 00000
Service (207) 555-0112 | service@graniteridge-ford.example

Repair Order RO # 6650291

Customer	UAT Sample Buyer	**Vehicle**	2023 Ford F-150 XLT SuperCrew 4x4
Address	69 Example Lane, Testville, ME 00000	**VIN**	1FTFW1E57PFA69021
Phone	(207) 555-0169	**Plate / color**	ME 6902-QA / Antimatter Blue
Opened	2026-01-14 08:05	**Odometer**	31,207 in / 31,209 out
Closed	2026-01-15 11:30	**Tag**	552
Advisor	Dana Whitcomb (#41)	**Tech**	see each line

Line 1: Safety recall 25S99 - rearview camera image software

Recall / campaign: Recall 25S99

Labor op	Tech	Pay	Description	Hours	Amount
25S99A	3381	R	Reprogram image processing module per recall 25S99	0.3	42.60

Line 2: Customer states fluid leak at rear axle

Warranty claim: Condition 42 | causal part 4676

Labor op	Tech	Pay	Description	Hours	Amount
4676B	3381	W	Replace rear axle pinion seal, refill axle	1.8	255.60
PART		W	SEAL - PINION OIL ML3Z-4676-A	1	22.40
PART		W	MOTORCRAFT SAE 75W-85 GEAR LUBE (QT) XY-75W85-QL	3	42.75

Synthetic test document (Stuffit UAT Scenario 69). Fictional shop, customer and transaction.

Line 3: Passenger heated seat inoperative

Warranty claim: Condition 31 | causal part 14D696

Labor op	Tech	Pay	Description	Hours	Amount
14D696B	2290	W	Replace RH front seat cushion heater element	1.6	227.20
PART		W	ELEMENT - SEAT HEATER ML3Z-14D696-B	1	168.35

Line 4: Multi-point inspection

Labor op	Tech	Pay	Description	Hours	Amount
MPI	3381	N	Multi-point inspection (no charge)		0.00

Billed to Ford Motor Co. (warranty & recall)	
Labor	525.40
Parts	233.50
TOTAL BILLED TO PAYER	**758.90**

Customer pay	
Labor	0.00
Parts	0.00
Shop charges / fees	0.00
Sales tax 5.5% (parts & shop charges)	0.00
CUSTOMER TOTAL	**0.00**

Pay types: C = customer pay, W = warranty, R = recall / campaign, G = goodwill, N = no charge.
All work on this repair order was performed under the Ford New Vehicle Limited Warranty or a Ford safety recall at no charge to the customer.
Warranty and recall amounts are shown for information; they are billed to Ford Motor Company, not to the customer.

Customer signature _____ Date _____

Synthetic test document (Stuffit UAT Scenario 69). Fictional shop, customer and transaction.