LAKESIDE SUBARU

900 Example Lake Road · Testville, ME 00000 · (207) 555-0115 · service@lakeside-subaru.example

SERVICE INVOICE
RO 77031

Vehicle	2022 Subaru Outback Premium	**VIN**	4S4BTACC5N3690311
Plate / color	ME 6903-QA / Autumn Green	**Odometer**	61,240 in / 61,248 out
Customer	UAT Sample Buyer	**Address**	69 Example Lane, Testville, ME 00000
Phone	(207) 555-0169	**Opened**	14-OCT-26 07:58
Closed	15-OCT-26 16:20	**Advisor**	S. Beaulieu
Tech	see each line		

LINE A CVT JUDDER / SHUDDER ON LIGHT ACCELERATION 15-30 MPH

COMPLAINT: CVT judder / shudder on light acceleration 15-30 mph
CAUSE: DTC P0841 STORED. LINE PRESSURE SENSOR OUT OF RANGE AT VALVE BODY.
CORRECTION: REPLACED CONTROL VALVE BODY PER TSB, EXCHANGED CVTF, PERFORMED LEARNING. ROAD TESTED 8 MI - OK.
AUTHORIZATION: SOA goodwill auth GW-2610-4471: 100% parts / 50% labor

Type	Op / Part #	Description	Qty/Hrs	Total	Cust. pay
LAB G	31-G-VB	Diagnose & replace CVT control valve body, CVTF exchange, learn	4.2	705.60	**352.80**
PRT G	31825AA	CONTROL VALVE BODY ASSY	1	1,184.00	**0.00**
PRT G	K0425Y0711	SUBARU HIGH TORQUE CVTF (QT)	6	100.80	**0.00**

LINE B 60,000 MILE SERVICE - SPARK PLUGS

COMPLAINT: 60,000 mile service - spark plugs
CAUSE: SCHEDULED MAINTENANCE
CORRECTION: REPLACED 4 PLUGS, GAPPED/TORQUED TO SPEC.

Type	Op / Part #	Description	Qty/Hrs	Total	Cust. pay
LAB C	60K-SP	Replace spark plugs	1.3	218.40	**218.40**
PRT C	22401AA811	SPARK PLUG	4	75.80	**75.80**

Synthetic test document (Stuffit UAT Scenario 69). Fictional shop, customer and transaction.

LINE C BRAKE FLUID EXCHANGE

COMPLAINT: Brake fluid exchange
CAUSE: SCHEDULED MAINTENANCE
CORRECTION: FLUSHED AND BLED SYSTEM.

Type	Op / Part #	Description	Qty/Hrs	Total	Cust. pay
LAB C	60K-BF	Brake fluid exchange	0.7	117.60	**117.60**
PRT C		BRAKE FLUID DOT3 (32 OZ)	1	14.25	**14.25**

LINE D MULTI-POINT INSPECTION & COMPLIMENTARY WASH

COMPLAINT: Multi-point inspection & complimentary wash

Type	Op / Part #	Description	Qty/Hrs	Total	Cust. pay
LAB N	MPI	MPI - ALL OK; COMPLIMENTARY CAR WASH		0.00	**0.00**

Shop charges

SHOP SUPPLIES	16.00
HAZMAT / DISPOSAL	4.50

Billed to Subaru of America (goodwill)	
Labor	352.80
Parts	1,284.80
TOTAL BILLED TO PAYER	**1,637.60**

Customer pay	
Labor	688.80
Parts	90.05
Shop charges / fees	20.50
Sales tax 5.5% (parts & shop charges)	6.08
CUSTOMER TOTAL	**805.43**

Pay types: C = customer pay, W = warranty, R = recall / campaign, G = goodwill, N = no charge.
Goodwill assistance is a one-time accommodation by Subaru of America, Inc. outside the powertrain limited warranty and does not extend any warranty.

Customer signature _____ Date _____