Hillside Garage & A/C

240 Example Hill Road, Testville, ME 00000 • (207) 555-0120 • hillside-garage.example

INVOICE

Invoice #HG-24518 • Apr 9, 2025

Vehicle	2022 Subaru Outback Premium	**VIN**	4S4BTACC5N3690311
Plate / color	ME 6903-QA / Autumn Green	**Odometer**	41,120 in / 41,126 out
Customer	UAT Sample Buyer	**Address**	69 Example Lane, Testville, ME 00000
Phone	(207) 555-0169	**Writer**	Nina Ross
Tech	Omar Haddad (ASE A4/A7)		

Job 1 | A/C not cold - performance check & recharge — 223.95

Labor: A/C performance test, evacuate, vacuum hold & recharge (1.0 h @ $125.00/h)	125.00
Part: Refrigerant R-1234yf (lb) - 1 x $89.00	89.00
Part: UV leak dye - 1 x $9.95	9.95

Job 2 | CVT fluid exchange — 282.00

Labor: CVT fluid exchange (drain/fill x2), temp check (1.2 h @ $125.00/h)	150.00
Part: Subaru High Torque CVTF (qt) - 8 x $16.50	132.00

Job 3 | Rear differential fluid — 89.50

Labor: Rear differential fluid change (0.5 h @ $125.00/h)	62.50
Part: Gear oil 75W-90 GL-5 (qt) - 2 x $13.50	27.00

Job 4 | Headlamp bulb — 43.99

Labor: Replace headlamp bulb LH low (0.2 h @ $125.00/h)	25.00
Part: Bulb H11 low beam - 1 x $18.99	18.99

Job 5 | State inspection — 18.50

Fee: State safety inspection (sticker #0000-TEST)	18.50

Shop charges

Shop supplies	10.00

Customer pay	
Labor	362.50
Parts	276.94
Shop charges / fees	28.50
Sales tax 5.5% (parts & shop charges)	15.78
CUSTOMER TOTAL	**683.72**

Recommend: brake fluid exchange next visit. A/C held vacuum 15 min, vent temp 41 F after service.

Customer signature _____ Date _____

Synthetic test document (Stuffit UAT Scenario 69). Fictional shop, customer and transaction.