仅支持 MX150!

简介

根据 [Guide] Alternative to the minStolenSize patch with 32mb DVMT-prealloc, Broadwell/Skylake/KabyLake 平台上一个常见问题是 PC 厂商设定了相对较小的动态显存。苹果的帧缓存驱动通常假定动态显存在 64mb 或以上,然而大部分 PC 厂商只有 32mb 动态显存。因此,在 EFI 里我们通过给帧缓存打补丁来让系统适配 32mb 动态显存。

然而,我发现在小米笔记本 $Pro \perp$,32mb 动态显存似乎不支持 4K 显示,添加 -cdfon 启动参数也不管用。设置 64mb 动态显存并移除动态显存补丁可以让我们的机器支持原生 4K。

怎么安装

Cyb 和 FallenChromium 创建了设置动态显存的脚本。请下载 DVMT_and_0xE2_fix 并阅读 README 中文版 来设置 64mb 动态显存。

注意: HDMI 接口使用的是 HDMI 1.4 协议,似乎只支持 4K 30 赫兹 HDMI。

然后你需要移除动态显存补丁:

- Clover 和 OC 用户都可用:
- 打开 /EFI/CLOVER (或者 OC)/config.plist 删除以下代码并重启:

```
<key>framebuffer-fbmem</key>
<data>AACQAA==</data>
<key>framebuffer-stolenmem</key>
<data>AAAwAQ==</data>
```

• 然后修改 framebuffer-flags 来开启 FBEnableDynamicCDCLK

```
<key>framebuffer-flags</key>
- <data>CwfDAA==</data>
+ <data>CwfjAA==</data>
```

• 可选, 更改 ig-platform-id 为 0x05001c59 (macOS 版本高于 10.14) 来提升显卡表现

```
<key>AAPL,ig-platform-id</key>
<data>AAAWWQ==</data>
<data>BOAcWQ==</data>
<key>AAPL,slot-name</key>
<string>Internal</string>
<key>complete-modeset-framebuffers</key>
<data>AAAAAAAAAE=</data>
<key>device-id</key>
<data>FlkAAA==</data>
<key>force-online</key>
<data>AQAAAA==</data>
<key>force-online-framebuffers</key>
<data>AAAAAAAAAE=</data>
<key>framebuffer-con0-enable</key>
<data>AQAAAA==</data>
<key>framebuffer-con0-flags</key>
<data>mAQAAA==</data>
<key>framebuffer-con1-enable</key>
<data>AQAAAA==</data>
<key>framebuffer-con1-flags</key>
<data>xwMAAA==</data>
```

鸣谢

- Rehabman
 - [Guide] Alternative to the minStolenSize patch with 32mb DVMT-prealloc
- Cyb 和 FallenChromium