



ENVIRONMENTAL INCIDENT REPORT - ETHYLENE GLYCOL SPILL - VERNAL

Report Taken By:	Morgan Atkinson by NRC		
Date / Time Reported:	10/27/2020 17:45		

REPORTING PARTY DATES AND TIMES

Reporting Party:	Tyler Esplin	Title:	
Company:	Deseret Power Electric Coop	Phone:	(435) 781-5706
Date & Time Discovered:	10/27/2020 17:25		

RESPONSIBLE PARTY

Name:	Deseret Power Electric COOP	Phone:	(435) 781-5706
Address:	12500 East 2500 South, Vernal, UT		

INCIDENT LOCATION

Incident Address:	12500 East 25500 South		
Nearest Town:	VERNAL	County:	UINTAH
Highway:		Mile Marker:	
UTM:	(E) 646129 (N) 4438908	Land Ownership:	Private

INCIDENT SUMMARY

From the NRC Report:
DESCRIPTION OF INCIDENT
CALLER IS REPORTING WHILE TRANSFERRING AN ETHYLENE GLYCOL MIX FROM A HEATING UNIT. A HOSE SPLIT CAUSING A RELEASE OF THE ETHYLENE GLYCOL AND WATER ONTO THE GROUND. CALLER STATES THE AMOUNT RELEASED IS AROUND 25000 POUNDS.

REMEDIAL ACTIONS
ABSORBENTS APPLIED, MATERIAL CONTAINED, VAC TRUCK USED, EXCAVATED SOIL, CLEAN UP CREW ON-SITE, CLEAN UP UNDERWAY
Release Secured: YES

No waterways are impacted and no injuries.

CHEMICAL(S) REPORTED

Antifreeze 25000 Pounds

IMPACTED MEDIA	Media	Media Other	Land Use	Waterway Name	Near Water	Distance	NRC Rpt. #
	Hard Surface (Asphalt/Cement)	N/A	Industrial	N/A		N/A	1290829

NOTIFICATIONS MADE	Agency	Contact	Date	Time	By	Active?
	DEQ DE	Nathan Hall	10/27/2020	18:50	MPA	Active
	Tri-County HD	Dispatch	10/27/2020	19:00	MPA	
	DWMRC	Deborah Ng	10/27/2020	19:05	MPA	

Incident notification reports are prepared by DEQ staff using information provided by the reporting party. The information is considered preliminary and is subject to revision. The reported incident and associated details may or may not be valid



Utah Department of Environmental Quality
Division of Environmental Response and Remediation
195 North 1950 West Salt Lake City, Utah 84116
Bus. Hours: 801-536-4100
Report Spills 24/7/365: 801-536-4123

Report Number 14702

ACTIONS TAKEN	Date	Agency	Action	Action Details
	10/11/2022	DEQ DE	Incident Closure	No Action Needed - Spill to concrete cleaned up, meets the Quick Site Cleanup Standards outlined in the 2014 Spills Workgroup recommendations.