



ENVIRONMENTAL INCIDENT REPORT - DUCHESNE COUNTY - CRUDE OIL RELEASE

Report Taken By:	Michael Swistak		
Date / Time Reported:	1/30/2023 14:0		

REPORTING PARTY DATES AND TIMES

Reporting Party:	Josh Morgan	Title:	Operations Tech
Company:	Uinta Wax Operating	Phone:	(817) 231-8756
Date & Time Discovered:	1/29/2023 12:0		

RESPONSIBLE PARTY

Name:	Uinta Wax Operating	Phone:	(817) 231-8756
Address:			

INCIDENT LOCATION

Incident Address:			
Nearest Town:	MYTON	County:	DUCHESNE
Highway:		Mile Marker:	
UTM:	(E) 592418 (N) 4448771	Land Ownership:	Private

INCIDENT SUMMARY

Water was being put down the wellhead to help the oil to flow better; however, things weren't connected properly and caused 1 barrel of crude oil to be release onto soils. Contaminated soil was cleaned up and hauled to Brennan Bottom Disposal. Caller is notifying UDOGM and BLM.

CHEMICAL(S) REPORTED

	Crude Oil 1 Barrels
	Production Water 5 Barrels

IMPACTED MEDIA	Media	Media Other	Land Use	Waterway Name	Near Water	Distance	NRC Rpt. #
	Soils	N/A	Oil & Gas Production Field	N/A		N/A	N/A
	Roadway	N/A	Mixed Use	N/A		N/A	N/A

NOTIFICATIONS MADE

	Agency	Contact	Date	Time	By	Active?
	Tri-County HD	Sara	1/30/2023	16:20	Michael Swistak	Active
	DOGM	Lisha Cordova	1/30/2023	16:35	Michael Swistak	
	DEQ DE	Nathan Hall	1/30/2023	16:30	Michael Swistak	
	DWQ	Samantha Heusser	2/23/2023	10:30	crb	Active



Utah Department of Environmental Quality
Division of Environmental Response and Remediation
195 North 1950 West Salt Lake City, Utah 84116
Bus. Hours: 801-536-4100
Report Spills 24/7/365: 801-536-4123

Report Number 16109

ACTIONS TAKEN	Date	Agency	Action	Action Details
	5/25/2023	DEQ DE	Site Visit	evaluate cleanup
	5/25/2023	DEQ DE	Incident Closure	Informal note in database - For the first event, the spill appeared to be contained to the DOGM permitted pad. The second event meets the DWQ quick site cleanup.
	2/23/2023	DERR	Update	02/23/2023 10:04: Josh Morgan (Uinta Wax) reported the incident included the release of 5 barrels of production water in addition to the release of 1 barrel crude oil. The release occurred during two events; the release at the well as described in the initial report; and, a second event where a hot oiler truck spilled crude oil and production water to the dirt roadway as it was leaving the location. The contaminated soils in the roadway were excavated and disposed as in the initial report.