



## ENVIRONMENTAL INCIDENT REPORT - MYTON -- PRODUCED WATER SPILL

|                       |                 |  |  |
|-----------------------|-----------------|--|--|
| Report Taken By:      | Kevin Okleberry |  |  |
| Date / Time Reported: | 6/30/2021 17:55 |  |  |

### REPORTING PARTY DATES AND TIMES

|                         |                      |        |                             |
|-------------------------|----------------------|--------|-----------------------------|
| Reporting Party:        | Sid Thayne           | Title: | Field Environmental Advisor |
| Company:                | Newfield Exploration | Phone: | (435) 646-4858              |
| Date & Time Discovered: | 6/30/2021 12:0       |        |                             |

### RESPONSIBLE PARTY

|          |                                            |        |                |
|----------|--------------------------------------------|--------|----------------|
| Name:    | Newfield Exploration                       | Phone: | (435) 646-4858 |
| Address: | 10530 S. County Road 33, Myton, Utah 84052 |        |                |

### INCIDENT LOCATION

|                   |                             |                 |          |
|-------------------|-----------------------------|-----------------|----------|
| Incident Address: | Tar Sand 4-30-8-17 SLB Line |                 |          |
| Nearest Town:     | MYTON                       | County:         | DUCHESNE |
| Highway:          |                             | Mile Marker:    |          |
| UTM:              | (E) 580556 (N) 4438752      | Land Ownership: | BLM      |
|                   |                             |                 |          |

### INCIDENT SUMMARY

An underground steel pipeline developed a leak and discharged an estimated 216 barrels of produced water. The water seeped up to the surface, accumulated next to a road, and flowed into a dry drainage. No surface water was impacted.

### CHEMICAL(S) REPORTED

|                              |
|------------------------------|
| Production Water 216 Barrels |
|------------------------------|

| IMPACTED MEDIA | Media | Media Other | Land Use                   | Waterway Name | Near Water | Distance | NRC Rpt. # |
|----------------|-------|-------------|----------------------------|---------------|------------|----------|------------|
|                | Soils | N/A         | Oil & Gas Production Field | N/A           |            | N/A      | N/A        |

| NOTIFICATIONS MADE | Agency        | Contact         | Date      | Time  | By              | Active? |
|--------------------|---------------|-----------------|-----------|-------|-----------------|---------|
|                    | BLM           | Brian Barnett   | 6/30/2021 | 17:30 | Reporting Party | Active  |
|                    | DOGM          | Mike Perkins    | 6/30/2021 | 17:30 | Reporting Party | Active  |
|                    | DEQ DE        | Nathan Hall     | 6/30/2021 | 17:55 | Reporting Party | Active  |
|                    | DWQ           | Kevin Okleberry | 6/30/2021 | 17:55 | Reporting Party | Active  |
|                    | Tri-County HD | Darrin Brown    | 7/1/2021  | 08:30 | kmo             | Active  |

| ACTIONS TAKEN | Date     | Agency | Action           | Action Details                                  |
|---------------|----------|--------|------------------|-------------------------------------------------|
|               | 9/9/2021 | DWQ    | Incident Closure | NFA/Closure letter sent to RP - DWQ-2021-017790 |

Incident notification reports are prepared by DEQ staff using information provided by the reporting party. The information is considered preliminary and is subject to revision. The reported incident and associated details may or may not be valid



Utah Department of Environmental Quality  
Division of Environmental Response and Remediation  
195 North 1950 West Salt Lake City, Utah 84116  
Bus. Hours: 801-536-4100  
Report Spills 24/7/365: 801-536-4123

**Report Number 15015**

| ACTIONS TAKEN | Date     | Agency | Action             | Action Details                                             |
|---------------|----------|--------|--------------------|------------------------------------------------------------|
|               | 9/2/2021 | DWQ    | Cleanup completed  | Received cleanup reports (DWQ-2021-017792, 017794, 017796) |
|               | 7/6/2021 | DEQ DE | Site Visit         | Found extent of flow path                                  |
|               | 7/1/2021 | DWQ    | DWQ No Enforcement | Evaluated incident, no DWQ enforcement.                    |