



ENVIRONMENTAL INCIDENT REPORT - RANDLETT- NATURAL GAS AND CONDENSATE

Report Taken By:	Hannah Tremble-Marty		
Date / Time Reported:	6/8/2023 15:15		

REPORTING PARTY DATES AND TIMES

Reporting Party:	Josh Morgan	Title:	Operations Tech
Company:	Uinta Wax Operating	Phone:	(817) 231-8756
Date & Time Discovered:	6/8/2023 13:0		

RESPONSIBLE PARTY

Name:	Uinta Wax Operating	Phone:	(000) 000-0000
Address:			

INCIDENT LOCATION

Incident Address:			
Nearest Town:	RANDLETT	County:	UINTAH
Highway:		Mile Marker:	
UTM:	(E) 601243 (N) 4449106	Land Ownership:	Private

INCIDENT SUMMARY

Uinta Wax Operating has a gas sales line that separated at a weld point. The line break released approximately half a barrel of condensate, and about 15 mcf of natural gas. A crew is on their way to the location at the time of reporting. They will repair the weld, collect the contaminated soil, and dispose of the soil at EEI disposal. If needed the crew apply microblaze to impacted vegetation.

No storm drains or waterways impacted by the release.

The reporting party has notified the private land owner, and plans to contact UDOGM following this notification.

CHEMICAL(S) REPORTED

	Natural Gas 15 Other: (Describe) MCF
	Other: (describe) Condensate 0.5 Barrels

IMPACTED MEDIA

	Media	Media Other	Land Use	Waterway Name	Near Water	Distance	NRC Rpt. #
	Soils	N/A	Oil & Gas Production Field	N/A		N/A	N/A

NOTIFICATIONS MADE

	Agency	Contact	Date	Time	By	Active?
	DAQ	Jay Morris	6/8/2023	15:35	HTM	Active
	DWMRC	Deborah Ng	6/8/2023	15:40	HTM	Active
	Tri-County HD	Sarah	6/8/2023	15:45	HTM	



Utah Department of Environmental Quality
Division of Environmental Response and Remediation
195 North 1950 West Salt Lake City, Utah 84116
Bus. Hours: 801-536-4100
Report Spills 24/7/365: 801-536-4123

Report Number 16373

ACTIONS TAKEN	Date	Agency	Action	Action Details
	7/7/2023	DAQ	Incident Closure	No Action Needed - Incident appeared to be addressed properly and is not within AO/PBR site.