



ENVIRONMENTAL INCIDENT REPORT - VERNAL- DRILLING MUD

Report Taken By:	Hannah Tremble-Marty		
Date / Time Reported:	3/30/2023 7:45		

REPORTING PARTY DATES AND TIMES

Reporting Party:	George Hilvers	Title:	
Company:	Andeavor Field Services	Phone:	(304) 841-5730
Date & Time Discovered:	3/29/2023 15:30		

RESPONSIBLE PARTY

Name:	Andeavor Field	Phone:	
Address:			

INCIDENT LOCATION

Incident Address:			
Nearest Town:	VERNAL	County:	UINTAH
Highway:		Mile Marker:	
UTM:	(E) 634028 (N) 4439864	Land Ownership:	BLM

INCIDENT SUMMARY

A contractor for the reporting party is working on building a pipeline and they are boring a section using a horizontal directional drill. During the boring process an inadvertent release of boring mud (water and NSF-60 bentonite) occurred. The total amount released is unknown, but estimated at 1,000 gallons. The mud flowed down what is normally a dry wash, but due to the snowmelt there is water in the wash. The material flowed roughly 200 yards, and was stopped right before it entered an ephemeral stream.

The contractor on site placed silt fence and waddle to contain the release with additional checks placed along the wash. They are working on further containment and clean-up this morning.

A representative from the land department of the responsible party is contacting the BLM.

CHEMICAL(S) REPORTED

Other: (describe) NSF-60 Bentonite + Water 1,000 Gallons
--

IMPACTED MEDIA	Media	Media Other	Land Use	Waterway Name	Near Water	Distance	NRC Rpt. #
	Surface Water	N/A	Oil & Gas Production Field	Unknown/Not named	In Surface Water	N/A	N/A

NOTIFICATIONS MADE	Agency	Contact	Date	Time	By	Active?
	DWQ	Samantha Heusser	3/30/2023	08:15	HTM	Active
	DEQ DE	Nathan Hall	3/30/2023	08:30	HTM	Active

ACTIONS TAKEN	Date	Agency	Action	Action Details
---------------	------	--------	--------	----------------