



ENVIRONMENTAL INCIDENT REPORT - LEETON - CRUDE OIL SPILL

Report Taken By:	Edoardo Tagliaferri		
Date / Time Reported:	3/5/2024 14:45		

REPORTING PARTY DATES AND TIMES

Reporting Party:	David Buckalew	Title:	Environmental Foreman
Company:	Finely Resources, Inc	Phone:	(435) 790-2950
Date & Time Discovered:	3/5/2024 9:0		

RESPONSIBLE PARTY

Name:	Finely Resources, Inc	Phone:	(435) 790-2950
Address:	978 Crescent Rd, Roosevelt, UT 84066		

INCIDENT LOCATION

Incident Address:			
Nearest Town:	LEETON	County:	UINTAH
Highway:		Mile Marker:	
UTM:	(E) 591655 (N) 4470900	Land Ownership:	Private

INCIDENT SUMMARY

At oil well location RU 19D-24 a pressure release valve released, misting crude oil into the air; 3 barrels worth were contained but approximately 30 gallons sprayed over the containment berm and onto the surrounding soil. A clean-up crew has been dispatched today by Finley. UDOGM was contacted by reporting party, the report number is 8477. The release did not come into contact with any drainages or water.

CHEMICAL(S) REPORTED

Crude Oil 30 Gallons

IMPACTED MEDIA	Media	Media Other	Land Use	Waterway Name	Near Water	Distance	NRC Rpt. #
	Soils	N/A	Oil & Gas Production Field	N/A		N/A	N/A

NOTIFICATIONS MADE	Agency	Contact	Date	Time	By	Active?
	DWMRC	Deborah Ng	3/5/2024	15:30	Edoardo Tagliaferri	Active
	Tri-County HD	Kathy	3/5/2024	15:35	Edoardo Tagliaferri	

ACTIONS TAKEN	Date	Agency	Action	Action Details
	4/9/2024	DWMRC	Report received	
	4/9/2024	DWMRC	Incident Closure	Informal note in database - Per report from RP, cleanup and remediation is completed.
	3/28/2024	DWMRC	Update	Requested final report from RP.



Utah Department of Environmental Quality
Division of Environmental Response and Remediation
195 North 1950 West Salt Lake City, Utah 84116
Bus. Hours: 801-536-4100
Report Spills 24/7/365: 801-536-4123

Report Number 16942

ACTIONS TAKEN	Date	Agency	Action	Action Details
	3/20/2024	DWMRC	Update	DOGM reported that onsite spill is <5 bbls and do not require DOGM inspection/closure. Portion of the spill that sprayed off-site is still open pending cleanup and remediation report by RP.