



ENVIRONMENTAL INCIDENT REPORT - VERNAL -- HYDRAULIC FLUID RELEASE

Report Taken By:	Liberty Coe		
Date / Time Reported:	3/29/2024 5:35		

REPORTING PARTY DATES AND TIMES

Reporting Party:	Derek Richards	Title:	Production Supervisor
Company:	Simplot Inc	Phone:	(435) 828-0765
Date & Time Discovered:	3/28/2024 22:0		

RESPONSIBLE PARTY

Name:	Simplot Inc	Phone:	(435) 781-3331
Address:	9401 North Highway 191 Vernal		

INCIDENT LOCATION

Incident Address:	9401 North Highway 191		
Nearest Town:	VERNAL	County:	UINTAH
Highway:		Mile Marker:	
UTM:	(E) 629658 (N) 4494775	Land Ownership:	Private

INCIDENT SUMMARY

40 gallons of heavy weight hydraulic fluid spilled onto the soil when a fitting blew off a pipe at a mining facility. The line has been shut off. Remediation has not taken place but will be completed once crews arrive to fix the fitting which should be sometime today (3/29).

No surface water or storm drains were impacted.

CHEMICAL(S) REPORTED

	Hydraulic Oil 40 Gallons
--	--------------------------

IMPACTED MEDIA	Media	Media Other	Land Use	Waterway Name	Near Water	Distance	NRC Rpt. #
	Soils	N/A	Industrial	N/A		N/A	N/A

NOTIFICATIONS MADE	Agency	Contact	Date	Time	By	Active?
	DWMRC	Deborah Ng	3/29/2024	05:45	Liberty Coe	
	DAQ	Jay Morris	3/29/2024	05:45	Liberty Coe	
	Tri-County HD	Group Email	3/29/2024	05:50	Liberty Coe	
	DEQ DE	Nathan Hall	3/29/2024	05:50	Liberty Coe	

ACTIONS TAKEN	Date	Agency	Action	Action Details
	4/4/2024	DWMRC	Report received	
	4/4/2024	DWMRC	Incident Closure	Informal note in database - Per final report, cleanup and remediation has been completed.

Incident notification reports are prepared by DEQ staff using information provided by the reporting party. The information is considered preliminary and is subject to revision. The reported incident and associated details may or may not be valid



Utah Department of Environmental Quality
Division of Environmental Response and Remediation
195 North 1950 West Salt Lake City, Utah 84116
Bus. Hours: 801-536-4100
Report Spills 24/7/365: 801-536-4123

Report Number 16986