



ENVIRONMENTAL INCIDENT REPORT - UPDATE VERNAL -- PRODUCTION WATER SPILL

Report Taken By:	Ryan Curtin		
Date / Time Reported:	1/7/2021 15:40		

REPORTING PARTY DATES AND TIMES

Reporting Party:	Ben Shoup	Title:	Environmental Consultant
Company:	Absaroka Energy and Environmental Solutions	Phone:	(307) 299-5950
Date & Time Discovered:	1/5/2021 17:40		

RESPONSIBLE PARTY

Name:	Citation Oil and Gas	Phone:	(281) 891-1000
Address:	14077 Cutten Road, Houston, Texas 77069		

INCIDENT LOCATION

Incident Address:	WHU #6 Well		
Nearest Town:	VERNAL	County:	UINTAH
Highway:		Mile Marker:	
UTM:	(E) 648532 (N) 4453510	Land Ownership:	BLM

INCIDENT SUMMARY

8 barrel produced water leak from a water injection line. The line was buried, spill affected only the sediment in the barrow ditch. The flow line has been replaced, cleanup has not yet been cleaned

CHEMICAL(S) REPORTED

Production Water 8 Barrels

IMPACTED MEDIA	Media	Media Other	Land Use	Waterway Name	Near Water	Distance	NRC Rpt. #
	Soils	N/A	Oil & Gas Production Field	N/A		N/A	N/A

NOTIFICATIONS MADE

Agency	Contact	Date	Time	By	Active?
DOGM	Richard Powell	1/7/2021	14:00	Ben Shoup	
DWQ	Kevin Okleberry	1/7/2021	14:30	Ben Shoup	
BLM	Johnny Bouwen	1/6/2021	08:50	Ben Shoup	

ACTIONS TAKEN	Date	Agency	Action	Action Details
	2/2/2021	DWQ	Incident Closure	NFA/Closure letter sent to RP - DWQ-2021-001301
	1/26/2021	DWQ	Cleanup completed	Received cleanup report (DWQ-2021-001303)
	1/8/2021	DEQ DE	Site Visit	Located extent of spill path - probably more than 8 barrels
	1/7/2021	DWQ	DWQ No Enforcement	Evaluated incident, no DWQ enforcement.

Incident notification reports are prepared by DEQ staff using information provided by the reporting party. The information is considered preliminary and is subject to revision. The reported incident and associated details may or may not be valid



Utah Department of Environmental Quality
Division of Environmental Response and Remediation
195 North 1950 West Salt Lake City, Utah 84116
Bus. Hours: 801-536-4100
Report Spills 24/7/365: 801-536-4123

Report Number 14768