



ENVIRONMENTAL INCIDENT REPORT - OURAY -- CRUDE OIL SPILL

Report Taken By:	Kevin Okleberry		
Date / Time Reported:	10/12/2021 11:5		

REPORTING PARTY DATES AND TIMES

Reporting Party:	Josh Morgan	Title:	Operations Tech
Company:	Finley Resources	Phone:	(817) 231-8756
Date & Time Discovered:	10/10/2021 12:0		

RESPONSIBLE PARTY

Name:	Uinta Wax Operating	Phone:	(817) 336-1924
Address:	5128 Apache Plume Rd, Ste 300 Fort Worth, TX 76109		

INCIDENT LOCATION

Incident Address:	Ute Tribal 32-04-4-3E API #43-047-56652		
Nearest Town:	OURAY	County:	UINTAH
Highway:		Mile Marker:	
UTM:	(E) 611992 (N) 4439631	Land Ownership:	Tribal

INCIDENT SUMMARY

A failed gasket on the burner tube caused a 10 barrel oil spill on the Ute Tribal 32-04-4-3E (43-047-56652).
The contaminated soil was hauled to the Brennan Bottom disposal and microblaze was spread on the spray that landed outside of containment.

CHEMICAL(S) REPORTED

	Crude Oil 10 Barrels
--	----------------------

IMPACTED MEDIA	Media	Media Other	Land Use	Waterway Name	Near Water	Distance	NRC Rpt. #
	Soils	N/A	Oil & Gas Production Field	N/A		N/A	N/A

NOTIFICATIONS MADE

	Agency	Contact	Date	Time	By	Active?
	DWQ	Kevin Okleberry	10/12/2021	11:05	Reporting Party	Active
	DEQ DE	Nathan Hall	10/12/2021	14:25	kmo	Active
	Tri-County HD	Darrin Brown	10/12/2021	14:25	kmo	Active
	DOGM	Chase Hanberg	10/12/2021	14:25	kmo	Active

ACTIONS TAKEN	Date	Agency	Action	Action Details
	10/13/2021	DWQ	DWQ No Enforcement	Tribal Land, no DWQ enforcement.
	10/13/2021	DWQ	Incident Closure	No Action Needed -