



ENVIRONMENTAL INCIDENT REPORT - ROOSEVELT- DIESEL RELEASE

Report Taken By:	HTM		
Date / Time Reported:	12/17/2023 12:20		

REPORTING PARTY DATES AND TIMES

Reporting Party:	Eric Morton	Title:	Principal Geologist
Company:	Broadbent and Associates	Phone:	(530) 518-3437
Date & Time Discovered:	12/17/2023 8:30		

RESPONSIBLE PARTY

Name:	Pilot (or potentially 3rd party delivery company)	Phone:	
Address:			

INCIDENT LOCATION

Incident Address:	380 S 200 E		
Nearest Town:	ROOSEVELT	County:	DUCHESNE
Highway:		Mile Marker:	
UTM:	(E) 585895 (N) 4460925	Land Ownership:	Private

INCIDENT SUMMARY

During fuel delivery something was not connected correctly (the reporting party suspects it was a cam-lock) resulting in 50-70 gallons of diesel spilling to hard surfaces at Pilot Truck Stop #140.

Staff on scene placed drysweep on the impacted area, and Lincoln Environmental has been contracted to complete the clean-up. As far as the reporting party is aware, no storm drains were impacted by the release.

CHEMICAL(S) REPORTED

Diesel 70 Gallons

IMPACTED MEDIA	Media	Media Other	Land Use	Waterway Name	Near Water	Distance	NRC Rpt. #
	Hard Surface (Asphalt/Cement)	N/A	Commercial	N/A		N/A	N/A

NOTIFICATIONS MADE

	Agency	Contact	Date	Time	By	Active?
	DERR	Morgan Atkinson	12/17/2023	13:00	HTM	Active
	Tri-County HD	Darrin Brown	12/17/2023	13:05	HTM	Active

ACTIONS TAKEN	Date	Agency	Action	Action Details
	3/1/2024	DERR	Incident Closure	Resolved - Release OJO assigned to Mark Crim for DERR/PST regulatory oversight. NFA issued 2/7/2024.



Utah Department of Environmental Quality
Division of Environmental Response and Remediation
195 North 1950 West Salt Lake City, Utah 84116
Bus. Hours: 801-536-4100
Report Spills 24/7/365: 801-536-4123

Report Number 16823

ACTIONS TAKEN	Date	Agency	Action	Action Details
	12/19/2023	DERR	Update	Another responding group assigned EnviroCare (Ryan Tune) to complete the clean-up, and Broadbent and Associates asked Lincoln Environmental to not respond. Roosevelt City applied dirt to soak up the diesel, and it has been hauled away from the site. An unknown quantity of diesel did enter a storm drain on site, and has been cleaned up according to EnviroCare.